INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

ate: 6 30 2024 Time: 8 15	AU	Type of	Inspection:	Weekly Z	Storm Ev	rent □
GENERAL INFORMATION:	POND	1	POND 2		POND 3	
	NORMAL 🗆		NORMAL 🗆		NORMAL 🗹	
1) Water Level in Pond	HIGH LOW		HIGH LOW		HIGH LOW	
2) Is Ash Being Removed?	YES 🗆	NO 🗹	YES 🗆	NO Z	YES 🗆	NO 🗹
3) In Service?	YES 🗆	NO 🔽	YES 🗆	NO 🗹	YES 🗹	NO 🗆
PHYSICAL INSPECTION:		•				
 Seepage from or through embankment? Includes roads around ponds and outside fence. 	YES 🗆	NO 🗸	YES 🗆	NO 🗹	YES 🗆	NO 🗹
2) Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO 🗸	YES 🗆	NO 🗷	YES 🗆	NO 🗇
3) Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🛮	YES 🗆	NO 🛭	YES 🗆	NO 🖵
4) Cracking on Embankments/Berms?	YES 🗆	NO 🗹	YES 🗆	NO 🖵	YES 🗆	NO 🖵
5) Animal Burrows on embankments?	YES 🗆	NO 🖵	YES 🗆	NO 🗹	YES 🗆	NO 🗹
6) Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO 🗹	YES 🗆	NO 🗗	YES 🗆	NO 🖵
7) Slope Erosion on berms or embankments?	YES 🗆	NO 🗆	YES 🗆	NO 🗷	YES 🗆	NO 🖊
8) Debris on embankments/berms?	YES 🗆	NO 🗹	YES 🗆	NO 📮	YES 🗆	NO 🖳
Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🗗	YES 🗆	NO 📮	YES 🗆	NO 🗹
10) Visible Releases	YES 🗆	NO 🗹	YES 🗆	NO 🗷	YES 🗆	NO 🗆

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain:
12) Is there any damage to Pond Liner: YES \(\square\) NO \(\square\)
12.a) If YES, Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES □ N/A □
12.e) Notified Shift Supervisor of Damage? YES Date Notified: N/A
12.f) Notified Station Management of Damage? YES Date Notified: N/A
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION POND 2 Gauge Marking (ft) 4-2 (In Tenth's of Feet)
FOND 2 Gauge Marking (ft) 4-2 (In Tenth's of Feet) Elevation FT/MSL 521.7
Gauge Marker Instrument is in good condition and readable YES NO
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print):
Inspector Signature

INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

Date:	7-3-24 Time: 7.4	-3-24 Time: 7:45 Am		Inspection:	Weekly 🔽	/eekly 🛛 Storm Eve		
GE	NERAL INFORMATION:	POND	1	POND	2	POND 3		
		NORMAL 🗆		NORMAL 🗆		NORMAL 💢		
1)	Water Level in Pond	HIGH		HIGH		HIGH		
		LOW	₩	LOW	风	LOW		
2)	Is Ash Being Removed?	YES 🗆	NO 💆	YES 🗆	NO 🗵	YES 🗆	NO 🔀	
3)	In Service?	YES 🗆	NO ⊠	YES 🗆	NO 🗵	YES 🛚	NO 🗆	
<u>PH</u>	YSICAL INSPECTION:		•					
1)	Seepage from or through embankment? Includes roads around ponds and outside fence.	YES 🗆	NO ⊠	YES 🗆	NO 🗵	YES 🗆	NO ⊠	
2)	Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO ☑	YES 🗆	NO ⊠	YES 🗆	NO 🛣	
3)	Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🔀	YES 🗆	NO 🗵	YES 🗆	NO 🖾	
4)	Cracking on Embankments/Berms?	YES 🗆	NO Ø	YES 🗆	NO 🔀	YES 🗆	NO 🗵	
5)	Animal Burrows on embankments?	YES 🗆	NO 🗵	YES 🗆	NO 🗵	YES 🗆	NO 🏻	
6)	Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO 🗷	YES 🗆	NO 🏻	YES 🗆	NO 🛚	
7)	Slope Erosion on berms or embankments?	YES 🗆	ио ⊠	YES 🗆	NO 🖾	YES 🗆	NO 🛛	
8)	Debris on embankments/berms?	YES 🗆	ио ⊠	YES 🗆	NO 💆	YES 🗆	NO ⊠	
9)	Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🗵	YES 🗆	NO 🔀	YES 🗆	NO ⊠	

YES 🗆

NO 🔯

YES 🗆

NO 🖾

10) Visible Releases

NO ⊠

YES 🗆

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain:
12) Is there any damage to Pond Liner: YES □ NO ☒
12.a) If YES, Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES \square N/A \square
12.e) Notified Shift Supervisor of Damage? YES Date Notified: N/A
12.f) Notified Station Management of Damage? YES Date Notified: N/A
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION
POND 2 Gauge Marking (ft) (In Tenth's of Feet)
Elevation FT/MSL 520,6
Gauge Marker Instrument is in good condition and readable YES ⋈ NO □
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print):
Inspector Signature: