INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

Pate: 14,2024 Time:		Type of	Inspection:	Weekly J	Storm Ev	vent 🗆
GENERAL INFORMATION:	POND	POND 1		POND 2		
1) Water Level in Pond	NORN HIGH LOW	MAL	NORN HIGH LOW	IAL 🗆	NORN HIGH LOW	AL Z
2) Is Ash Being Removed?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
3) In Service?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗹	NO 🗆
PHYSICAL INSPECTION:		•				
Seepage from or through embankment? Includes road around ponds and outside fe	I	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO □
2) Sinkholes/Depressions/Bulge Pond or embankments?	es in YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
3) Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
4) Cracking on Embankments/Berms?	YES 🗆	NO 🔀	YES 🗆	NO □	YES 🗆	NO 🗹
5) Animal Burrows on embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🛮
6) Excessive or Lacking Vegetat Cover on embankments? (sh be normal growth)	1	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
7) Slope Erosion on berms or embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗸
8) Debris on embankments/be	rms? YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
Deterioration, malfunctions, improper operation of overtopping control systems	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
10) Visible Releases	YES 🗆	NO 🗸	YES 🗆	NO 📝	YES 🗆	NO 🗆

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain:
12) Is there any damage to Pond Liner: YES \(\sigma\) NO \(\sigma\)
12.a) If YES, Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES \square N/A \square
12.e) Notified Shift Supervisor of Damage? YES Date Notified: N/A
12.f) Notified Station Management of Damage? YES \Box Date Notified: N/A \Box
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION
POND 2 Gauge Marking (ft) (In Tenth's of Feet)
Elevation FT/MSL 519.5
Gauge Marker Instrument is in good condition and readable YES NO
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print):
Inspector Signatu

INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

ate: 7/17/24 Time: 9:30	AM	Type of	Inspection:	Weekly 🔀	Storm Ev	ent 🗆
GENERAL INFORMATION:	POND	1	POND	2	POND 3	
1) Water Level in Pond	NORM HIGH	IAL 🗆	NORIV HIGH	IAL 🗆	NORM HIGH	IAL 🛮
	LOW		LOW		LOW	
2) Is Ash Being Removed?	YES 🗆	NO 🌠	YES 🗆	NO 🗹	YES 🗆	NO 🔽
3) In Service?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗹	NO 🗆
PHYSICAL INSPECTION:	-					
Seepage from or through embankment? Includes roads around ponds and outside fence.	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
2) Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO 🗹	YES 🗹	NO 🗆	YES 🗆	NO 🗸
3) Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
4) Cracking on Embankments/Berms?	YES 🗆	NO 🗹	YES 🗆	NO ₫	YES 🗆	NO 🗹
5) Animal Burrows on embankments?	YES 🗆	NO 🗹	YES 🗆	ио ₫	YES 🗆	NO 🗹
6) Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO 🗹	YES 🗆	NO 🇹	YES 🗆	NO ✓
7) Slope Erosion on berms or embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 📈
8) Debris on embankments/berms?	YES 🗆	NO 🗹	YES 🗆	NO Z	YES 🗆	NO 🗹
9) Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
10) Visible Releases	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗸

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain MONSTORENG DEPRESSION N.E. CORNER, NO CHA	n: <u>fond 2</u> NGE
12) Is there any damage to Pond Liner: YES \(\square\) NO	
12.a) If YES, Describe in Detail:	
12.b) Specific Location:	
12.c) Is Water Level Below Damage? YES □ NO □	
12.d) If No, Did You Reduce Pond Level? YES \square N/A \square	
12.e) Notified Shift Supervisor of Damage? YES Date Notified:	N/A □
12.f) Notified Station Management of Damage? YES Date Notified:	
OND LEVEL INSTRUMENTATION	
OND 2 Gauge Marking (ft) 2.4 (In Tenth's of Feet)	
levation FT/MSL 519.9	
Sauge Marker Instrument is in good condition and readable YES W NO	
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are condu	icted as part of
nspector Name (Print):	
nspector Name (Frint).	