INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

ate:	7/28/24 Time: 11:0	DAM	Type of	Inspection:	Weekly 🖟	Storm Ev	ent 🗆
<u>GE</u>	NERAL INFORMATION:	POND	1	POND	2	POND 3	
		NORMAL 🗆		NORMAL 🗆		NORMAL 🗆	
1)	Water Level in Pond	HIGH LOW		HIGH LOW		HIGH	
2)	Is Ash Being Removed?	YES 🗆	NO ☑	YES 🗆	NO 🗷	YES 🗆	NO ☑
3)	In Service?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🔽	NO 🗆
PH	YSICAL INSPECTION:		•				
1)	Seepage from or through embankment? Includes roads around ponds and outside fence.	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
2)	Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO 🗹	YES 🗹	NO 🗆	YES 🗆	NO 🗹
3)	Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🗹	YES 🗆	NO ☑	YES 🗆	NO 🗹
4)	Cracking on Embankments/Berms?	YES 🗆	NO 🗹	YES 🗆	NO ☑	YES 🗆	NO 🗷
5)	Animal Burrows on embankments?	YES 🗆	NO 🔽	YES 🗆	NO 🗹	YES 🗆	NO 🔽
6)	Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹
7)	Slope Erosion on berms or embankments?	YES 🗆	NO 🗹	YES 🗆	NO ☑	YES 🗆	NO ⊻
8)	Debris on embankments/berms?	YES 🗆	NO 🖻	YES 🗆	NO 🔼	YES 🗆	NO 🗹
9)	Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🔨

NO 🗹

YES 🗆

YES 🗆

NO N

10) Visible Releases

YES

NO 🗹

11) If Yes to any of the ab						
12) Is there any damage t	o Pond Liner:	YES 🗆	NO 🗹			
12.a) If YES, Describe in	n Detail:			70 Y		. = *,
12.b) Specific Location	· ·					
12.c) Is Water Level Be		YES 🗆 NO) []			
12.e) Notified Shift S			· ·	tified:	r	N/A □
12.f) Notified Station	Management of	Damage?	YES 🗆 Dat	e Notified:	•	_ N/A 🗆
12.g) Additional Com	ments:					
	6/					
POND LEVEL INSTRUMENT	ATION					
POND 2 Gauge Marking (fit Elevation FT/MSL $\frac{5/9}{}$	_	n Tenth's o	f Feet)			
Gauge Marker Instrument	is in good condition	on and read	lable YES		NO 🗆	
NOTE: Joliet 29 Pond 1 & F Operations Best Practices	Pond 3 are not CCR	Surface Im	poundments	. Inspection	ns are condu	cted as part of
		(2)				
Inspector Name (Print):						
Inspector Signature:						

				0		

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

ate: 7/31/24 Time: 9:0	OAM	Type of	Inspection:	Weekly 🔽	Storm Ev	ent 🗆	
GENERAL INFORMATION:	POND	1	POND	2	POND 3		
	NORM	NORMAL		NORMAL 🗆		NORMAL 🗹	
1) Water Level in Pond	HIGH		HIGH LOW		HIGH LOW		
2) Is Ash Being Removed?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	
3) In Service?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🔽	№ □	
PHYSICAL INSPECTION:		•				363	
Seepage from or through embankment? Includes roads around ponds and outside fence	YES 🗆	NO ₹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	
2) Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO Z	YES 🗹	NO 🗆	YES 🗆	NO 🗹	
 Signs of Piping/Channels or other Internal Erosion on embankments? 	YES 🗹	NO 🗆	YES 🗆	NO 🗹	YES 🗆	NO 🕡	
4) Cracking on Embankments/Berms?	YES 🗆	NO 🗹	YES 🗆	NO ☑	YES 🗆	NO 🗹	
5) Animal Burrows on embankments?	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	
6) Excessive or Lacking Vegetative Cover on embankments? (shoul be normal growth)	d YES 🗆	NO 🗹	YES 🗆	NO ✓	YES 🗆	NO 🗹	
7) Slope Erosion on berms or embankments?	YES 🗆	NO 🗹	YES 🗆	NO <table-cell></table-cell>	YES 🗆	NO 🗹	
8) Debris on embankments/berms	? YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	
Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	
10) Visible Releases	YES 🗆	NO 🗹	YES 🗆	NO 🗹	YES 🗆	NO 🗹	

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain: POND EROSION CHANNELS ON ACCESS RAMP INTO POND. POND #2 - BOOK DEPRESSION N.E., CORVER - NO CHANGE
12) Is there any damage to Pond Liner: YES NO
12.a) If YES, Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES \(\square\) N/A \(\square\)
12.e) Notified Shift Supervisor of Damage? YES □ Date Notified: N/A □
12.f) Notified Station Management of Damage? YES Date Notified: N/A
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION
POND 2 Gauge Marking (ft) 2,2 (In Tenth's of Feet)
Elevation FT/MSL 519.7
Gauge Marker Instrument is in good condition and readable YES 🗹 NO 🗆
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print):
Inspector Signature: