WEEKLY QUALIFIED PERSON CHECK LIST FOR JOLIET 29 ASH PONDS

INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to <u>6.45 inches</u>.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

<u>Date</u> :	3-2-25 Time: 08	<u>30</u>	Type of	Inspection:	Weekly 🗷	Storm Ev	vent □
GEI	NERAL INFORMATION:	POND 1		POND 2		POND 3	
1)	Water Level in Pond	NORMAL □		NORMAL □		NORMAL ⊅ HIGH □	
-,	Trace Ecremin one	LOW	<u>□</u>	LOW	<u></u>	LOW	
2)	Is Ash Being Removed?	YES 🗆	NO ⊠	YES 🗆	NO 🔁	YES 🗆	NO ⊠
3)	In Service?	YES 🗆	NO 🗵	YES 🗆	NO ⅓	YES 🗵	NO 🗆
PH	YSICAL INSPECTION:						
1)	Seepage from or through embankment? Includes roads around ponds and outside fence.	YES 🗆	NO 🗹	YES 🗆	NO ⊠	YES 🗆	NO ⊠
2)	Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO ₹	YES 🗆	NO 🗵	YES 🗆	NO ⊠
3)	Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO 🔀	YES 🗆	NO 🔀	YES 🗆	NO ₽
4)	Cracking on Embankments/Berms?	YES 🗆	ио 🖄	YES 🗆	NO ₹	YES 🗆	NO 🛱
5)	Animal Burrows on embankments?	YES 🗆	NO DE	YES 🗆	NO 🗗	YES 🗆	NO 🔯
6)	Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO Þ⁄	YES 🗆	NO 💆	YES 🗆	NO 🎏
7)	Slope Erosion on berms or embankments?	YES 🗆	NO ⊠	YES 🗆	NO D	YES 🗆	NO D
8)	Debris on embankments/berms?	YES 🗆	NO 🔀	YES 🗆	NO 💆	YES 🗆	NO 🔯
9)	Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO ₹	YES 🗆	NO ⅓	YES 🗆	NO ⊠
10) Visible Releases	YES 🗆	NO 🛛	YES 🗆	NO ₹	YES 🗆	NO 🕅

12) Is there any damage to Pond Liner: YES \(\Boxed{\subset}\) NO \(\boxed{\subset}\)
If YES, answer questions below:
12.a) Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES □ N/A □
12.e) Notified Shift Supervisor of Damage? YES Date Notified: N/A
12.f) Notified Station Management of Damage? YES Date Notified: N/A
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION POND 2 Gauge Marking (ft) (In Tenth's of Feet)
Elevation FT/MSL 5 19.6
Gauge Marker Instrument is in good condition and readable YES 💆 NO 🗌
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print):
Inspector Signature: _

WEEKLY QUALIFIED PERSON CHECK LIST FOR JOLIET 29 ASH PONDS

INSTRUCTIONS:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted weekly and within 24 hours after a storm event greater or equal to 6.45 inches.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years.
- 3) Every week, the qualified person must also inspect the CCR Unit Instrumentation.

Date:	3-5-25 Time: 080	<u>C</u>	Type of	Inspection:	Weekly 🔉	Storm Ev	ent 🗆
GENERAL INFORMATION:		POND 1		POND 2		POND 3	
1)	Water Level in Pond	NORMAL □ HIGH □ LOW ☑		NORMAL □ HIGH □ LOW ☑		NORMAL HIGH □ LOW □	
2)	Is Ash Being Removed?	YES 🗆	NO ⅓	YES 🗆	NO ⋤	YES 🗆	NO Ø
3)	In Service?	YES 🗆	NO ⊠	YES 🗆	NO 🗹	YES 💆	NO 🗆
PH	YSICAL INSPECTION:			an agai			
1)	Seepage from or through embankment? Includes roads around ponds and outside fence.	YES 🗆	NO ⊠	YES 🗆	NO 🗵	YES 🗆	NO ⅓
2)	Sinkholes/Depressions/Bulges in Pond or embankments?	YES 🗆	NO ☑	YES 🗆	NO 🗵	YES 🗆	NO 록
3)	Signs of Piping/Channels or other Internal Erosion on embankments?	YES 🗆	NO ₹	YES 🗆	NO 🗷	YES 🗆	NO Ş
4)	Cracking on Embankments/Berms?	YES 🗆	NO 🗷	YES 🗆	NO 🗵	YES 🗆	NO 🗵
5)	Animal Burrows on embankments?	YES 🗆	NO 🗓	YES 🗆	NO 🖫	YES 🗆	NO 🗷
6)	Excessive or Lacking Vegetative Cover on embankments? (should be normal growth)	YES 🗆	NO ⅓	YES 🗆	NO 🔽	YES 🗆	NO ⊠
7)	Slope Erosion on berms or embankments?	YES 🗆	ио №	YES 🗆	NO 🛛	YES 🗆	NO 🗵
8)	Debris on embankments/berms?	YES 🗆	NO ¥	YES 🗆	NO 🗵	YES 🗆	NO 💆
9)	Deterioration, malfunctions, or improper operation of overtopping control systems	YES 🗆	NO 🔀	YES 🗆	NO ☑	YES 🗆	NO Þ
10	N Visible Releases	YES 🗆	NO 🕅	YES 🗆	NO 🔀	YES 🗆	NO 🗹

11) If Yes to any of the above, or any other abnormalities are noted, please describe/explain:
12) Is there any damage to Pond Liner: YES □ NO 💆
If YES, answer questions below:
12.a) Describe in Detail:
12.b) Specific Location:
12.c) Is Water Level Below Damage? YES □ NO □
12.d) If No, Did You Reduce Pond Level? YES \square N/A \square
12.e) Notified Shift Supervisor of Damage? YES Date Notified: N/A
12.f) Notified Station Management of Damage? YES Date Notified: N/A
12.g) Additional Comments:
POND LEVEL INSTRUMENTATION POND 2 Gauge Marking (ft) 2.4 (In Tenth's of Feet) Elevation FT/MSL 519.9
Gauge Marker Instrument is in good condition and readable YES ☑ NO □
NOTE: Joliet 29 Pond 1 & Pond 3 are not CCR Surface Impoundments. Inspections are conducted as part of Operations Best Practices
Inspector Name (Print): _
Inspector Signature: