WEEKLY SUMMARY REPORT

Week Ending: 09/05/2024 (Thursday)

Report No.: W-04-090524

Page 1 of 3

• N/A



Page 1 01 3		CIVII & I	Environmental Consultants, Inc.
PROJECT INFORM	ATION		
PROJECT NAME:	BYPASS BASIN RETROFIT CQA		
LOCATION:	Powerton Generating Station	CEC PROJECT NO:	343-014.0200
PLANS AND SPECS:	S&L Bypass Basin Retrofit Project	WEATHER:	Mostly Sunny
ISSUED DATE:	07/12/24	TEMP. RANGE (°F)	54-81
PERSONNEL			
FIELD REP(S):	Derek Dorsz	CEC PROJ. MANAGER(S):	Dean Jones
CLIENT:	Midwest Generation	CLIENT CONTACT(S):	Joe Kotas
CONTRACTOR:	Bluff City Construction (BCC)	SUPERVISOR:	Larry Hunt
CONTRACTOR:	Clean Air and Water Systems (CAAWS)	_SUPERVISOR:	Andy Khamarlorm
SAFETY MEETING	S AND PARTICIPATION		
	or's Tailgate Safety Meeting? 🗆 Yes 🗵 I	No Vehicle Check Performed? ⊠	Yes or No
	(WSM 200.25): ☐ Yes (CLICK LINK BE		
, 1		,	
WORK PERFORME	D SINCE CEC'S LAST VISIT(1)		
1 2	CEC representative's last site visit? $^{(1)}$ [
	ve was last onsite: Saturday, August 2 iring continuous observation that has been completed without		was not made aware that this work was being
completed.	iring continuous observation that has been completed without	CEC representation being present onsite. CEC	was not made aware that this work was being
SUMMARY OF WOI	RK OBSERVED, LOCATION, A	ND CONTRACTOR PER	FORMING WORK
BCC completed	sand filter layer within the basin floor.		
	per sand cushion layer along top perime		
1 *	6" protective warning layer within the		
	sand filter layer along the north and eas		
	rip rap bedding layer along north and eaupled sump riser pipe.	ast slopes of the basin.	
• BCC electio co	upled sump fiser pipe.		
UNEXPECTED, UN	USUAL, OR NONCONFORMIN	G OBSERVATIONS (NE	W / RESOLVED)
Unexpected, unusual, or • N/A	r nonconforming work observed? Yes	es 🛮 No	
SUMMARY OF MEE	ETINGS / DISCUSSIONS / PHO	NE CONVERSATIONS	
	s meeting Thursday, 9/5/24.		
	<i>5</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
ATTACHMENTS			

WEEKLY SUMMARY REPORT

Week Ending: 09/05/2024 (Thursday)

Page 2 of 3



DESCRIPTION OF SAMPLES TAKEN OR MATERIALS DELIVERED TO LAB

- PBBR-Sand-2 collected from sand filter layer.
- PBBR-PWL-1 collected from protective warning layer.
- PBBR-RB-1 collected from rip rap bedding layer.

PHOTOGRAPHS



Photo 1: shows completed sand filter layer along bottom of basin.



Photo 2: shows completed protective warning layer and placement of sand filter along slopes.

* No representations or warranties are made regarding the accuracy of the information generated by the Theodolite application, which is stamped on the photo, or the suitability of that information for any; legal, engineering, surveying, or other use or purpose.

WEEKLY SUMMARY REPORT

Week Ending: 09/05/2024 (Thursday)

Page 3 of 3





Photo 3: shows placement of rip rap bedding layer along eastern slope.



Photo 4: shows basin with protective warning layer and rip rap bedding layer.

APPROVED BY

FIELD REP: Derek Dorsz DATE: 09/05/2024 CEC MANAGER: Dean Jones DATE: 09/06/2024

This document is draft until reviewed and approved by a Project Manager

NOTICE: Our firm's professionals are represented onsite solely to observe operations of the contractor identified to form opinions about the adequacy of those operations and to report those opinions to our client. The presence and activities of our field representative do not relieve the contractor from its obligation to meet contractual requirements. The contractor retains sole responsibility for site safety and the methods operations and sequences of construction.

* No representations or warranties are made regarding the accuracy of the information generated by the Theodolite application, which is stamped on the photo, or the suitability of that information for any; legal, engineering, surveying, or other use or purpose.