Check List for Waukegan Ash Ponds

Instructions:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted every 7 days. To ensure compliance the inspection will be completed every Monday, Wednesday, and Friday.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years. Qualified Person list is filed at G:\Ops\Ash Pond Inspection
- 3) This is for all active and inactive CCR ponds. Inactive ponds are required to be maintained with water levels below 1 foot.
- 4) Every 30 days, the qualified person must also inspect the CCR Unit Instrumentation

	N /////	EAST AS	H POND	WES	ST ASH POND
1	General Condition: (Empty/Full)	F			٤
2	Water Level in Pond: (Normal or High/Low)	N			L
3	Is Ash Being Removed? (Y/N)	N			N
4	In Service? (Y/N)	Y			N
	Insti	rumentation C	heck		
	Sluice Return Pump	A		В	С
		(YES) N	IO (YES)	NO	XES NO
5	Pump in Good Condition	×	K		*
	<u> </u> Feder	ral CCR Evalu	ations		
	<u>Feder</u>		,	WE	ST ASH POND
	Feder		ations SH POND NO	WE:	ST ASH POND
7	Seepage from or through embankment?	EAST AS	SH POND		
7		EAST AS	SH POND		NO
	Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or	EAST AS	SH POND		NO
8	Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	EAST AS	SH POND		NO

		les	NO	405	MO
12	Excessive or Lacking Vegetative Cover on embankments?	X		×	B
13	Slope Erosion on berms or embankments?		X		X
14	Debris on embankments/berms?		X		X
15	If Yes to any of the above, or any other above			scribe/explain:	/
	Excessive veget				
İ		EAST A	SH POND	WEST AS	SH POND
		YES	NO	YES	NO
16	Visible damage to the Pond Liners		X		X
mu	TE: If there visible damage to the liner the st be notified immediately. IEPA notification below the water line	ion is require	d if the damage		
17	If YES, describe in detail (pond, specific loc	cation, size, et	c):		
		Yes	No	Nes	N6.
18	Is Water Level Below Damage (if damage is present)		Ž.		
19	If No, Reduce Pond Level and sign:				
20	Notified Shift Supv. of Damage and Sign:				
	Date Notified:				
21	Notified Station Management of Damage and Sign:				
	Date Notified:				
22	Additional Comments:	•			
	n n				
Ор	erator Name	Operator Si	gnature		_
TI	ME (2 : 30 AM PM Circle One)	DATE:	7,17	1 23	5. 5.
SH	IFT SUPERVISOR REVIEW				

Buckley, Jill

From: Brown, Michael

Sent: Monday, July 24, 2023 11:53 AM

To: Buckley, Jill

Subject: Logbook Entry - Complete

View Log Entry Details

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 10576265

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 07/19/2023 08:19:36.777 CDT

Log Entry Date / Time: 07/19/2023 08:19 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

Completed Items: 43 of 43

	<u>Title</u>	<u>Value</u>	<u>Timestamp</u>	Note
East Ash Pond	In Service	Yes	07/19/2023 07:48:01 CDT	
Ash Pond	General Condition	Empty	07/19/2023 07:48:23 CD	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0.79	07/19/2023 07:48:37 CDT	
Ash Pond	Is ash being removed	No	07/19/2023 07:48:40 CD	
West Ash Pond	In Service	No	07/19/2023 07:48:45 CDT	
mentation Checks	A Sluice Return Pump in good condition	Yes	07/19/2023 07:48:52 CD	
Instrumentation Checks	B Sluice Return Pump in good condition	Yes	07/19/2023 07:48:54 CDT	
mentation Checks	C Sluice Return Pump in good condition	Yes	07/19/2023 07:48:56 CD	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	07/19/2023 07:49:05 CDT	
R Evaluations	Ash Pond es/depressions/bulge or embankments	No	07/19/2023 07:49	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	07/19/2023 07:49:17 CDT	
R Evaluations	h Pond cracking on embankments/berms	No	07/19/2023 07:49:2	
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	07/19/2023 07:49:23 CDT	

R Evaluations	h Pond excessive or lacking vegetative cover on embankment	No	07/19/2023 07:49:
Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	07/19/2023 07:49:32 CDT
R Evaluations	h Pond debris on embankments/berms	No	07/19/2023 07:49:3
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	07/19/2023 07:47:22 CDT
al CCR Evaluations	East Ash Pond visible releases	No	07/19/2023 07:49:40 CD
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	07/19/2023 07:49:42 CDT
sh Pond	Visible damage to the pond liner	No	07/19/2023 07:50:58 CD
East Ash Pond	Is ash being removed	No	07/19/2023 07:47:51 CDT
ond	Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	6.19	07/19/2023 07:47:4
East Ash Pond	General Condition	Full	07/19/2023 07:47:41 CDT
Ash Pond Visible age to the pond liner	is water level below damage	NA	07/19/2023 07:47:
East Ash Pond Visible damage to the pond liner	Station Management notified	NA	07/19/2023 07:47:26 CDT
R Evaluations	t Ash Pond es/depressions/bulge or embankments	No	07/19/2023 07:49
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	07/19/2023 07:49:53 CDT
R Evaluations	sh Pond cracking on embankments/berms	No	07/19/2023 07:49:5
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	07/19/2023 07:49:59 CDT
R Evaluations	sh Pond excessive or lacking vegetative cover on embankments	No	07/19/2023 07:50:
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	07/19/2023 07:50:35 CDT
R Evaluations	sh Pond debris on embankments/berms	No	07/19/2023 07:50:
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	07/19/2023 07:47:24 CDT
al CCR Evaluations	West Ash Pond visible releases	No	07/19/2023 07:50:13 CD
West Ash Pond	Visible damage to the pond liner	No	07/19/2023 07:51:03 CDT
t Ash Pond Visible age to the pond liner	Is water level below damage	NA	07/19/2023 07:47:2
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	07/19/2023 07:47:27 CDT
t Ash Pond Visible age to the pond liner	Describe location and size	NA	07/19/2023 07:47:

West Ash Pond Visible Shamage to the pond liner	hift Supervisor notified	NA	07/19/2023 07:47:27 CDT
t Ash Pond Visible age to the pond liner	tation Management notified	NA	07/19/2023 07:47:2
East Ash Pond Visible damage to the pond liner Re damage	educed water level	NA	07/19/2023 07:47:25 CDT
Ash Pond Visible age to the pond liner	escribe location and size	NA	07/19/2023 07:47:
East Ash Pond Visible Shamage to the pond liner	hift Supervisor notified	NA	07/19/2023 07:47:26 CDT

Buckley, Jill

From: Brown, Michael

Sent: Monday, July 24, 2023 11:55 AM

To: Buckley, Jill

Subject: Logbook Entry - Complete

View Log Entry Details

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 10580095

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 07/21/2023 11:02:19.530 CDT

Log Entry Date / Time: 07/21/2023 11:00 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

Completed Items: 42 of 43

<u> </u>	<u>Title</u>	<u>Value</u>	<u>Timestamp</u>	<u>Note</u>
East Ash Pond	In Service	Yes	07/21/2023 10:58:26 CDT	
Ash Pond	General Condition	Empty	07/21/2023 10:58:30 CD	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0.87	07/21/2023 10:58:34 CDT	
Ash Pond	Is ash being removed	No	07/21/2023 10:58:36 CD	
West Ash Pond	In Service	No	07/21/2023 10:58:38 CDT	
rumentation	ce Return Pump in good condition	Yes	07/21/2023 10:58:4	
Instrumentation Checks	B Sluice Return Pump in good condition	Yes	07/21/2023 10:58:46 CDT	
rumentation cks	e Return Pump in good condition	Yes	07/21/2023 10:58:	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	07/21/2023 10:58:51 CDT	
sh Pond	Is ash being removed	No	07/21/2023 10:58:24 CD	
East Ash Pond	Water Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	6.01	07/21/2023 10:58:22 CDT	
sh Pond	General Condition	Full	07/21/2023 10:58:16 CD	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	07/21/2023 10:58:53 CDT	

Federal CCR Evaluations	East Ash Pond excessive or lacking vegetative cover on embankment	<u>Yes</u>	07/21/2023 10:59:07 CDT
Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	07/21/2023 10:59:17 CDT
eral CCR luations	sh Pond debris on embankments/berms		
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	07/21/2023 10:57:58 CDT
eral CCR luations	ast Ash Pond visible releases	No	07/21/2023 10:59:1
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	07/21/2023 10:59:23 CDT
sh Pond	Visible damage to the pond liner	No	07/21/2023 11:00:05
East Ash Pond Visible damage to the pond liner	is water level below damage	NA	07/21/2023 10:58:02 CDT
st Ash Pond damage to the s water vel below damage	ater level	NA	07/21/2023 10:5
East Ash Pond Visible damage to the pond liner	Describe location and size	NA	07/21/2023 10:58:02 CDT
st Ash Pond mage to the nd liner	pervisor notified	NA	07/21/2023 10:58
East Ash Pond Visible damage to the pond liner	Station Management notified	NA	07/21/2023 10:58:03 CDT
I CCR	t Ash Pond s/depressions/bulge pond or embankments	No	07/21/2023 10:59
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	07/21/2023 10:59:26 CDT
eral CCR luations	sh Pond cracking on embankments/berms	No	07/21/2023 10:59:
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	07/21/2023 10:59:31 CDT
<u>Federal CCR</u> <u>Evaluations</u>	West Ash Pond excessive or lacking vegetative cover on embankments	<u>Yes</u>	07/21/2023 10:59:38 CDT <u>Excessive</u> vegetation
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	07/21/2023 10:59:48 CDT
eral CCR luations	Ash Pond debris on embankments/berms	No	07/21/2023 10:59:5
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	07/21/2023 10:58:01 CDT
eral CCR luations	est Ash Pond visible releases	No	07/21/2023 10:59:

West Ash Pond	Visible damage to the pond liner	No	07/21/2023 11:00:08 CDT
est Ash Pond mage to the nd liner	level below damage	NA	07/21/2023 10:58
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	07/21/2023 10:58:04 CDT
est Ash Pond mage to the nd liner	e location and size	NA	07/21/2023 10:58
West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	07/21/2023 10:58:04 CDT
est Ash Pond mage to the nd liner	Management notified	NA	07/21/2023 10:58
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	07/21/2023 10:58:55 CDT
eral CCR luations	sh Pond cracking on embankments/berms	No	07/21/2023 10:58:5
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	07/21/2023 10:58:59 CDT