Waukegan Rounds Log 01/23/2025 07:32:38 CST

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 11741136

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 01/22/2025 11:56:10.337 CST

Log Entry Date / Time: 01/22/2025 11:55 CST **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

Completed Items: 40 of 40

Group	<u>Title</u>	Value	Timestamp	Note
East Ash Pond	General Condition	Full	01/22/2025 11:53:58 CST	
East Ash Pond	Water Level in Pond	0	01/22/2025 11:53:59 CST	
East Ash Pond	Is ash being removed	No	01/22/2025 11:54:01 CST	
East Ash Pond	In Service	No	01/22/2025 11:54:02 CST	
West Ash Pond	General Condition	Empty	01/22/2025 11:54:05 CST	
West Ash Pond	Water level in Pond	0	01/22/2025 11:54:07 CST	
West Ash Pond	Is ash being removed	No	01/22/2025 11:54:09 CST	
West Ash Pond	In Service	No	01/22/2025 11:54:10 CST	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	01/22/2025 11:54:24 CST	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	01/22/2025 11:54:26 CST	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	01/22/2025 11:54:28 CST	
Federal CCR Evaluations	East Ash Pond cracking on embankments/berms	No	01/22/2025 11:54:29 CST	
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	01/22/2025 11:54:31 CST	
Federal CCR Evaluations	East Ash Pond excessive or lacking vegetative cover on embankment	No	01/22/2025 11:54:33 CST	

Waukegan Rounds Log 01/23/2025 07:32:38 CST

Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	01/22/2025 11:54:34 CST
Federal CCR Evaluations	East Ash Pond debris on embankments/berms	No	01/22/2025 11:54:36 CST
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	01/22/2025 11:53:51 CST
Federal CCR Evaluations	East Ash Pond visible releases	No	01/22/2025 11:54:40 CST
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	01/22/2025 11:54:42 CST
East Ash Pond	Visible damage to the pond liner	No	01/22/2025 11:55:09 CST
East Ash Pond Visible damage to the pond liner	is water level below damage	NA	01/22/2025 11:53:51 CST
East Ash Pond Visible damage to the pond liner is water level below damage	Reduced water level	NA	01/22/2025 11:53:51 CST
East Ash Pond Visible damage to the pond liner	Describe location and size	NA	01/22/2025 11:53:51 CST
East Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	01/22/2025 11:53:52 CST
East Ash Pond Visible damage to the pond liner	Station Management notified	NA	01/22/2025 11:53:52 CST
Federal CCR Evaluations	West Ash Pond sinkholes/depressions/bulges in pond or embankments	No	01/22/2025 11:54:44 CST
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	01/22/2025 11:54:45 CST
Federal CCR Evaluations	West Ash Pond cracking on embankments/berms	No	01/22/2025 11:54:47 CST
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	01/22/2025 11:54:49 CST

Waukegan Rounds Log 01/23/2025 07:32:38 CST

Federal CCR Evaluations	West Ash Pond excessive or lacking vegetative cover on embankments	No	01/22/2025 11:54:51 CST
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	01/22/2025 11:54:54 CST
Federal CCR Evaluations	West Ash Pond debris on embankments/berms	No	01/22/2025 11:54:56 CST
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	01/22/2025 11:53:51 CST
Federal CCR Evaluations	West Ash Pond visible releases	No	01/22/2025 11:54:59 CST
West Ash Pond	Visible damage to the pond liner	No	01/22/2025 11:55:11 CST
West Ash Pond Visible damage to the pond liner	Is water level below damage	NA	01/22/2025 11:53:52 CST
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	01/22/2025 11:53:52 CST
West Ash Pond Visible damage to the pond liner	Describe location and size	NA	01/22/2025 11:53:52 CST
West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	01/22/2025 11:53:52 CST
West Ash Pond Visible damage to the pond liner	Station Management notified	NA	01/22/2025 11:53:52 CST

Check List for Waukegan Ash Ponds

Instructions:

- 1) An inspection of each ash pond and related embankments/berms at the Stations must be conducted every 7 days. To ensure compliance the inspection will be completed every Monday, Wednesday, and Friday.
- 2) The inspection must be conducted by a "qualified person" and the inspection records should be maintained at the Station for five years. Qualified Person list is filed at G:\Ops\Ash Pond Inspection
- 3) This is for all active and inactive CCR ponds. Inactive ponds are required to be maintained with water levels below 1 foot.
- 4) Every 30 days, the qualified person must also inspect the CCR Unit Instrumentation

	EAST ASH POND			WEST ASH POND			
General Condition: (Empty/Full)	Full			Empty			
Water Level in Pond: (Normal or High/Low)	Ø			Ø			
Is Ash Being Removed? (Y/N)	No			NO			
In Service? (Y/N)	NO		40				
Insti	<u>rumentati</u>	on Check					
Sluice Return Pump		A		В		C	
	YES	NO	YES	NO	YES	NO	
Pump in Good Condition	005	005	005	003	005	005	
sluice Return	n p	emp:		_ cos			
reuer				<u></u>			
	EAST ASH POND		WEST ASH POND				
	YES		NO	YES		NO	
Seepage from or through embankment?		>	X.			X	
Sinkholes/Depressions/Bulges in Pond or embankments?							
Signs of Piping/Channels or other Internal Erosion on embankments?			X	ıl.		<u> </u>	
,							
Cracking on Embankments/Berms?		(X			X	
	Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) Sluice Return Pump Pump in Good Condition If NO, Please describe condition and repairs Sluice Return Return Return Feder Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	General Condition: (Empty/Full) Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) Federal COS If NO, Please describe condition and repairs required: Sluice Return Pump Federal CCR E EAST YES Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	General Condition: (Empty/Full) Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) Sluice Return Pump A YES NO Pump in Good Condition OS OS If NO, Please describe condition and repairs required: Sluice Return Pump EAST ASH PO YES Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	General Condition: (Empty/Full) Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) NO In Service? (Y/N) NO Instrumentation Check Sluice Return Pump A YES NO YES Pump in Good Condition OS OS OS If NO, Please describe condition and repairs required: Sluice Return Pump Federal CCR Evaluations EAST ASH POND YES NO Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	General Condition: (Empty/Full) Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) In Service? (Y/N) A B YES NO Pump in Good Condition OS OS OS If NO, Please describe condition and repairs required: Sluice Return Pump East Ash Pond YES NO YES Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	General Condition: (Empty/Full) Water Level in Pond: (Normal or High/Low) Is Ash Being Removed? (Y/N) In Service? (Y/N) NO Instrumentation Check Sluice Return Pump A B YES NO YES NO YES Pump in Good Condition COS COS COS COS If NO, Please describe condition and repairs required: Sluice Return Federal CCR Evaluations Federal CCR Evaluations EAST ASH POND YES NO YES Seepage from or through embankment? Sinkholes/Depressions/Bulges in Pond or embankments? Signs of Piping/Channels or other Internal	

		<u>Yes</u>	No	Yes	NO	
12	Excessive or Lacking Vegetative Cover on embankments?		X		X	
13	Slope Erosion on berms or embankments?		X		X	
14	Debris on embankments/berms?		X		×	
15	If Yes to any of the above, or any other abno	ormalities are r	noted, please de	scribe/explain:		
				•		
		EAST AS	SH POND	WEST ASH POND		
4.5	N. N.	YES	NO	YES	NO	
16	Visible damage to the Pond Liners		X		Y	
444.04.	TE: If there visible damage to the liner the st be notified immediately. IEPA notification below the water line If YES, describe in detail (pond, specific loc	on is required	if the damage	nd the Operation is below or has t	as Manager the potential to	
18	Is Water Level Below Damage (if damage					
	is present)	NA				
19	If No, Reduce Pond Level and sign:	NA			,	
20	Notified Shift Supv. of Damage and Sign:					
	Date Notified:					
21	Notified Station Management of Damage and Sign:					
	Date Notified:					
22	Additional Comments:					
Operator Name:						
TIME 11: 30 AM PM (Circle One) DATE: 1 1 24 1 25						
SHIFT SUPERVISOR REVIEW:						