



Midwest Generation, LLC
Powerton Generating
Station
13082 East Manito Road
Pekin, IL 61554

NOTICE OF REMEDY –
OBSERVATION FROM INITIAL
ANNUAL INSPECTION REPORT 18 JANUARY 2016

Pursuant to 40 CFR 257.83(b), Geosyntec Consultants (Geosyntec) performed an annual inspection of the Ash Surge Basin and Bypass Basin at the Powerton Station in Pekin, Illinois (Figure 1). The inspection included a review of available information regarding the status and condition of the CCR units, a visual inspection of the CCR units, including hydraulic and appurtenant structures and preparation of the Initial Annual Inspection Report issued January 18, 2016. This report included one Structural/Operational Observation in regards to the Bypass Basin as follows:

“The outlet flume for the Bypass Basin overflow pipe, located along the southern slope of the Ash Surge Basin was observed to be partially filled with CCR. At the time of inspection (13 November 2015), the Bypass Basin was not actively receiving CCR. Although the potential to disrupt pond operations and safety is minimal, Geosyntec recommends removal of CCR deposits from this pipe as soon as feasible and prior to active operation of the Bypass Basin. Documentation of the CCR removal should be prepared in accordance with 40 CFR 257.83(b)(5). The documentation should be placed in the operating record and on the CCR web site, and notice should be provided to State Director per 40 CFR 257.83(b)(5), 257.105(g)(7), 257.106(g)(6), and 257.107(g)(6).”

On May 9, 2016, the outlet flume and the overflow pipe of the Bypass Basin were cleared using a high pressure water sprayer. The CCR material in the pipe was flushed into the Ash Surge Basin away from the pipe and will be disposed with the other CCR material next time the Ash Surge Basin is cleaned. The Bypass Basin, which only receives water when the Ash Surge Basin is out of service, was not receiving water from the time of the initial inspection to the time of the overflow pipe clearing.

A copy of this notice will be placed in the operating record and on the CCR website in accordance with 257.105(g)(7) and 257.107(g)(6), respectively. Additionally, a copy of this will be sent to the relevant Director of the Illinois Environmental Protection Agency in accordance with 257.106(g)(6).

Dale Green

Station Manager

Midwest Generation, LLC Powerton Station

5-26-2016

Date