

**Round: Ash Pond Inspection | Ash Pond Inspection**

**Entry ID:** 11495301

**Logbook Origination:** Waukegan Rounds

**Created By:** [REDACTED]

**System Timestamp:** 09/30/2024 11:54:43.860 CDT

**Log Entry Date / Time:** 09/30/2024 11:54 CDT

**Category:** Ash Pond Inspection | Ash Pond Inspection

**Event / Action:** Complete

**Completed Items:** 43 of 43

<u>Group</u>	<u>Title</u>	<u>Value</u>	<u>Timestamp</u>	<u>Note</u>
East Ash Pond	General Condition	Full	09/30/2024 11:50:47 CDT	
East Ash Pond	Water Level in Pond	0	09/30/2024 11:50:55 CDT	
East Ash Pond	Is ash being removed	No	09/30/2024 11:50:57 CDT	
East Ash Pond	In Service	No	09/30/2024 11:51:00 CDT	
West Ash Pond	General Condition	Empty	09/30/2024 11:51:04 CDT	
West Ash Pond	Water level in Pond	0	09/30/2024 11:51:05 CDT	
West Ash Pond	Is ash being removed	No	09/30/2024 11:51:08 CDT	
West Ash Pond	In Service	No	09/30/2024 11:51:10 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	09/30/2024 11:50:32 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	OOS	09/30/2024 11:50:32 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	09/30/2024 11:50:32 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	09/30/2024 11:51:18 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	09/30/2024 11:51:20 CDT	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	09/30/2024 11:51:21 CDT	

<b>Federal CCR Evaluations</b>	<b>East Ash Pond cracking on embankments/berms</b>	No	09/30/2024 11:51:23 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond animal burrows on embankments</b>	No	09/30/2024 11:51:25 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond excessive or lacking vegetative cover on embankment</b>	No	09/30/2024 11:51:26 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond slope erosion on berms or embankments</b>	No	09/30/2024 11:51:28 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond debris on embankments/berms</b>	No	09/30/2024 11:51:30 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond deterioration, malfunctions or improper operation of overtopping control system</b>	N/A	09/30/2024 11:50:33 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond visible releases</b>	No	09/30/2024 11:51:34 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond seepage from or through embankment (Copy)</b>	No	09/30/2024 11:51:37 CDT
<b>East Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	09/30/2024 11:52:04 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>is water level below damage</b>	NA	09/30/2024 11:50:34 CDT
<b>East Ash Pond   Visible damage to the pond liner   is water level below damage</b>	<b>Reduced water level</b>	NA	09/30/2024 11:50:34 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	09/30/2024 11:50:34 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	09/30/2024 11:50:34 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	09/30/2024 11:50:34 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond sinkholes/depressions/bulges in pond or embankments</b>	No	09/30/2024 11:51:38 CDT

<b>Federal CCR Evaluations</b>	<b>West Ash Pond signs of piping/channels or other internal erosion on embankment</b>	No	09/30/2024 11:51:40 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond cracking on embankments/berms</b>	No	09/30/2024 11:51:42 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond animal burrows on embankment</b>	No	09/30/2024 11:51:44 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond excessive or lacking vegetative cover on embankments</b>	No	09/30/2024 11:51:45 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond slope erosion on berms or embankments</b>	No	09/30/2024 11:51:48 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond debris on embankments/berms</b>	No	09/30/2024 11:51:51 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems</b>	N/A	09/30/2024 11:50:33 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond visible releases</b>	No	09/30/2024 11:51:53 CDT	
<b>West Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	09/30/2024 11:52:07 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Is water level below damage</b>	NA	09/30/2024 11:50:34 CDT	
<b>West Ash Pond   Visible damage to the pond liner   Is water level below damage</b>	<b>Reduced water level</b>	NA	09/30/2024 11:50:34 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	09/30/2024 11:50:34 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	09/30/2024 11:50:34 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	09/30/2024 11:50:34 CDT	

**Round: Ash Pond Inspection | Ash Pond Inspection**

**Entry ID:** 11497689

**Logbook Origination:** Waukegan Rounds

**Created By:** [REDACTED]

**System Timestamp:** 10/01/2024 12:05:12.520 CDT

**Log Entry Date / Time:** 10/01/2024 12:04 CDT

**Category:** Ash Pond Inspection | Ash Pond Inspection

**Event / Action:** Complete

**Completed Items:** 43 of 43

<u>Group</u>	<u>Title</u>	<u>Value</u>	<u>Timestamp</u>	<u>Note</u>
East Ash Pond	General Condition	Full	10/01/2024 11:56:36 CDT	
East Ash Pond	Water Level in Pond	0	10/01/2024 11:56:38 CDT	
East Ash Pond	Is ash being removed	No	10/01/2024 11:56:40 CDT	
East Ash Pond	In Service	No	10/01/2024 11:56:41 CDT	
West Ash Pond	General Condition	Empty	10/01/2024 11:56:45 CDT	
West Ash Pond	Water level in Pond	0	10/01/2024 11:56:47 CDT	
West Ash Pond	Is ash being removed	No	10/01/2024 11:56:48 CDT	
West Ash Pond	In Service	No	10/01/2024 11:56:50 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	10/01/2024 11:56:30 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	OOS	10/01/2024 11:56:30 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	10/01/2024 11:56:30 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	10/01/2024 11:56:58 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	10/01/2024 11:57:00 CDT	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	10/01/2024 11:57:03 CDT	

<b>Federal CCR Evaluations</b>	<b>East Ash Pond cracking on embankments/berms</b>	No	10/01/2024 11:57:05 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond animal burrows on embankments</b>	No	10/01/2024 11:57:06 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond excessive or lacking vegetative cover on embankment</b>	No	10/01/2024 11:57:08 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond slope erosion on berms or embankments</b>	No	10/01/2024 11:57:09 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond debris on embankments/berms</b>	No	10/01/2024 11:57:11 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond deterioration, malfunctions or improper operation of overtopping control system</b>	N/A	10/01/2024 11:56:30 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond visible releases</b>	No	10/01/2024 11:57:15 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond seepage from or through embankment (Copy)</b>	No	10/01/2024 11:57:17 CDT
<b>East Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/01/2024 11:57:53 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>is water level below damage</b>	NA	10/01/2024 11:56:31 CDT
<b>East Ash Pond   Visible damage to the pond liner   is water level below damage</b>	<b>Reduced water level</b>	NA	10/01/2024 11:56:31 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/01/2024 11:56:31 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/01/2024 11:56:31 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/01/2024 11:56:31 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond sinkholes/depressions/bulges in pond or embankments</b>	No	10/01/2024 11:57:18 CDT

<b>Federal CCR Evaluations</b>	<b>West Ash Pond signs of piping/channels or other internal erosion on embankment</b>	No	10/01/2024 11:57:20 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond cracking on embankments/berms</b>	No	10/01/2024 11:57:22 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond animal burrows on embankment</b>	No	10/01/2024 11:57:23 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond excessive or lacking vegetative cover on embankments</b>	No	10/01/2024 11:57:25 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond slope erosion on berms or embankments</b>	No	10/01/2024 11:57:27 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond debris on embankments/berms</b>	No	10/01/2024 11:57:29 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems</b>	N/A	10/01/2024 11:56:31 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond visible releases</b>	No	10/01/2024 11:57:31 CDT	
<b>West Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/01/2024 11:57:57 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Is water level below damage</b>	NA	10/01/2024 11:56:31 CDT	
<b>West Ash Pond   Visible damage to the pond liner   Is water level below damage</b>	<b>Reduced water level</b>	NA	10/01/2024 11:56:31 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/01/2024 11:56:31 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/01/2024 11:56:31 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/01/2024 11:56:31 CDT	

**Round: Ash Pond Inspection | Ash Pond Inspection****Entry ID:** 11500249**Logbook Origination:** Waukegan Rounds**Created By:** [REDACTED]**System Timestamp:** 10/02/2024 11:32:15.593 CDT**Log Entry Date / Time:** 10/02/2024 11:32 CDT**Category:** Ash Pond Inspection | Ash Pond Inspection**Event / Action:** Complete**Completed Items:** 43 of 43

<b><u>Group</u></b>	<b><u>Title</u></b>	<b><u>Value</u></b>	<b><u>Timestamp</u></b>	<b><u>Note</u></b>
East Ash Pond	General Condition	Full	10/02/2024 11:30:23 CDT	
East Ash Pond	Water Level in Pond	0	10/02/2024 11:30:25 CDT	
East Ash Pond	Is ash being removed	No	10/02/2024 11:30:27 CDT	
East Ash Pond	In Service	No	10/02/2024 11:30:28 CDT	
West Ash Pond	General Condition	Empty	10/02/2024 11:30:31 CDT	
West Ash Pond	Water level in Pond	0	10/02/2024 11:30:33 CDT	
West Ash Pond	Is ash being removed	No	10/02/2024 11:30:34 CDT	
West Ash Pond	In Service	No	10/02/2024 11:30:36 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	10/02/2024 11:30:15 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	OOS	10/02/2024 11:30:15 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	10/02/2024 11:30:15 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	10/02/2024 11:30:44 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	10/02/2024 11:30:46 CDT	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	10/02/2024 11:30:48 CDT	

<b>Federal CCR Evaluations</b>	<b>East Ash Pond cracking on embankments/berms</b>	No	10/02/2024 11:30:49 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond animal burrows on embankments</b>	No	10/02/2024 11:30:51 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond excessive or lacking vegetative cover on embankment</b>	No	10/02/2024 11:30:53 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond slope erosion on berms or embankments</b>	No	10/02/2024 11:30:54 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond debris on embankments/berms</b>	No	10/02/2024 11:30:59 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond deterioration, malfunctions or improper operation of overtopping control system</b>	N/A	10/02/2024 11:30:16 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond visible releases</b>	No	10/02/2024 11:31:01 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond seepage from or through embankment (Copy)</b>	No	10/02/2024 11:31:03 CDT
<b>East Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/02/2024 11:31:31 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>is water level below damage</b>	NA	10/02/2024 11:30:16 CDT
<b>East Ash Pond   Visible damage to the pond liner   is water level below damage</b>	<b>Reduced water level</b>	NA	10/02/2024 11:30:16 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/02/2024 11:30:16 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/02/2024 11:30:16 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/02/2024 11:30:16 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond sinkholes/depressions/bulges in pond or embankments</b>	No	10/02/2024 11:31:06 CDT



<b>Federal CCR Evaluations</b>	<b>West Ash Pond signs of piping/channels or other internal erosion on embankment</b>	No	10/02/2024 11:31:07 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond cracking on embankments/berms</b>	No	10/02/2024 11:31:09 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond animal burrows on embankment</b>	No	10/02/2024 11:31:11 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond excessive or lacking vegetative cover on embankments</b>	No	10/02/2024 11:31:14 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond slope erosion on berms or embankments</b>	No	10/02/2024 11:31:16 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond debris on embankments/berms</b>	No	10/02/2024 11:31:19 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems</b>	N/A	10/02/2024 11:30:16 CDT	
<b>Federal CCR Evaluations</b>	<b>West Ash Pond visible releases</b>	No	10/02/2024 11:31:22 CDT	
<b>West Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/02/2024 11:31:33 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Is water level below damage</b>	NA	10/02/2024 11:30:17 CDT	
<b>West Ash Pond   Visible damage to the pond liner   Is water level below damage</b>	<b>Reduced water level</b>	NA	10/02/2024 11:30:17 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/02/2024 11:30:17 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/02/2024 11:30:17 CDT	
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/02/2024 11:30:17 CDT	

**Round: Ash Pond Inspection | Ash Pond Inspection**

**Entry ID:** 11504914

**Logbook Origination:** Waukegan Rounds

**Created By:** [REDACTED]

**System Timestamp:** 10/04/2024 11:21:24.980 CDT

**Log Entry Date / Time:** 10/04/2024 11:21 CDT

**Category:** Ash Pond Inspection | Ash Pond Inspection

**Event / Action:** Complete

**Completed Items:** 43 of 43

<u>Group</u>	<u>Title</u>	<u>Value</u>	<u>Timestamp</u>	<u>Note</u>
East Ash Pond	General Condition	Empty	10/04/2024 11:18:21 CDT	
East Ash Pond	Water Level in Pond	0	10/04/2024 11:18:23 CDT	
East Ash Pond	Is ash being removed	No	10/04/2024 11:18:30 CDT	
East Ash Pond	In Service	No	10/04/2024 11:18:32 CDT	
West Ash Pond	General Condition	Empty	10/04/2024 11:18:48 CDT	
West Ash Pond	Water level in Pond	0	10/04/2024 11:18:53 CDT	
West Ash Pond	Is ash being removed	No	10/04/2024 11:18:55 CDT	
West Ash Pond	In Service	No	10/04/2024 11:18:58 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	10/04/2024 11:18:07 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	OOS	10/04/2024 11:18:07 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	10/04/2024 11:18:08 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	10/04/2024 11:19:14 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	10/04/2024 11:19:16 CDT	
Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	10/04/2024 11:19:18 CDT	

<b>Federal CCR Evaluations</b>	<b>East Ash Pond cracking on embankments/berms</b>	No	10/04/2024 11:19:20 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond animal burrows on embankments</b>	No	10/04/2024 11:19:23 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond excessive or lacking vegetative cover on embankment</b>	No	10/04/2024 11:19:25 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond slope erosion on berms or embankments</b>	No	10/04/2024 11:19:27 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond debris on embankments/berms</b>	No	10/04/2024 11:19:42 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond deterioration, malfunctions or improper operation of overtopping control system</b>	N/A	10/04/2024 11:18:08 CDT
<b>Federal CCR Evaluations</b>	<b>East Ash Pond visible releases</b>	No	10/04/2024 11:19:45 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond seepage from or through embankment (Copy)</b>	No	10/04/2024 11:19:47 CDT
<b>East Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/04/2024 11:20:58 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>is water level below damage</b>	NA	10/04/2024 11:18:09 CDT
<b>East Ash Pond   Visible damage to the pond liner   is water level below damage</b>	<b>Reduced water level</b>	NA	10/04/2024 11:18:09 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/04/2024 11:18:09 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/04/2024 11:18:09 CDT
<b>East Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/04/2024 11:18:09 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond sinkholes/depressions/bulges in pond or embankments</b>	No	10/04/2024 11:19:51 CDT

<b>Federal CCR Evaluations</b>	<b>West Ash Pond signs of piping/channels or other internal erosion on embankment</b>	No	10/04/2024 11:19:53 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond cracking on embankments/berms</b>	No	10/04/2024 11:20:00 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond animal burrows on embankment</b>	No	10/04/2024 11:20:04 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond excessive or lacking vegetative cover on embankments</b>	No	10/04/2024 11:20:07 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond slope erosion on berms or embankments</b>	No	10/04/2024 11:20:11 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond debris on embankments/berms</b>	No	10/04/2024 11:20:14 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems</b>	N/A	10/04/2024 11:18:08 CDT
<b>Federal CCR Evaluations</b>	<b>West Ash Pond visible releases</b>	No	10/04/2024 11:20:17 CDT
<b>West Ash Pond</b>	<b>Visible damage to the pond liner</b>	No	10/04/2024 11:21:02 CDT
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Is water level below damage</b>	NA	10/04/2024 11:18:09 CDT
<b>West Ash Pond   Visible damage to the pond liner   Is water level below damage</b>	<b>Reduced water level</b>	NA	10/04/2024 11:18:09 CDT
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Describe location and size</b>	NA	10/04/2024 11:18:09 CDT
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Shift Supervisor notified</b>	NA	10/04/2024 11:18:09 CDT
<b>West Ash Pond   Visible damage to the pond liner</b>	<b>Station Management notified</b>	NA	10/04/2024 11:18:09 CDT