Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 11241414

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 06/08/2024 06:57:29.930 CDT

Log Entry Date / Time: 06/08/2024 06:57 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

<u>Group</u>	<u>Title</u>	Value	<u>Timestamp</u>	<u>Note</u>
East Ash Pond	General Condition	Full	06/08/2024 06:48:50 CDT	
East Ash Pond	Water Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	1.13	<u>06/08/2024 06:49:43 CDT</u>	Sluice return pumps no longer in service.
East Ash Pond	Is ash being removed	No	06/08/2024 06:49:46 CDT	
East Ash Pond	In Service	No	06/08/2024 06:49:48 CDT	
West Ash Pond	General Condition	Empty	06/08/2024 06:49:52 CDT	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0	06/08/2024 06:49:55 CDT	
West Ash Pond	Is ash being removed	No	06/08/2024 06:49:56 CDT	
West Ash Pond	In Service	No	06/08/2024 06:49:58 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	06/08/2024 06:50:02 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	oos	06/08/2024 06:50:04 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	06/08/2024 06:50:05 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	06/08/2024 06:50:09 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/08/2024 06:50:11 CDT	

East Ash Pond signs of piping/channels or other internal erosion on embankments	No	06/08/2024 06:50:12 CDT	
East Ash Pond cracking on embankments/berms	No	06/08/2024 06:50:14 CDT	
East Ash Pond animal burrows on embankments	No	06/08/2024 06:50:16 CDT	
East Ash Pond excessive or lacking vegetative cover on embankment	<u>Yes</u>	<u>06/08/2024 06:50:33 CDT</u>	Excessive vegetation on south berm.
East Ash Pond slope erosion on berms or embankments	No	06/08/2024 06:50:39 CDT	
East Ash Pond debris on embankments/berms	No	06/08/2024 06:50:41 CDT	
East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	06/08/2024 06:48:43 CDT	
East Ash Pond visible releases	No	06/08/2024 06:50:44 CDT	
West Ash Pond seepage from or through embankment (Copy)	No	06/08/2024 06:50:46 CDT	
Visible damage to the pond liner	No	06/08/2024 06:51:35 CDT	
is water level below damage	NA	06/08/2024 06:48:44 CDT	
Reduced water level	NA	06/08/2024 06:48:44 CDT	
Describe location and size	NA	06/08/2024 06:48:44 CDT	
Shift Supervisor notified	NA	06/08/2024 06:48:44 CDT	
Station Management notified	NA	06/08/2024 06:48:44 CDT	
	piping/channels or other internal erosion on embankments East Ash Pond cracking on embankments/berms East Ash Pond animal burrows on embankments East Ash Pond excessive or lacking vegetative cover on embankment East Ash Pond slope erosion on berms or embankments East Ash Pond debris on embankments/berms East Ash Pond detrioration, malfunctions or improper operation of overtopping control system East Ash Pond seepage from or through embankment (Copy) Visible damage to the pond liner is water level below damage Reduced water level Describe location and size Shift Supervisor notified	piping/channels or other internal erosion on embankments East Ash Pond cracking on embankments/berms East Ash Pond animal burrows on embankments East Ash Pond excessive or lacking vegetative cover on embankment East Ash Pond slope erosion on berms or embankments East Ash Pond debris on embankments/berms East Ash Pond detrioration, malfunctions or improper operation of overtopping control system East Ash Pond seepage from or through embankment (Copy) Visible damage to the pond liner is water level below damage NA Reduced water level NA Shift Supervisor notified NA	piping/channels or other internal crosion on embankments East Ash Pond cracking on embankments/berms East Ash Pond animal burrows on embankments East Ash Pond excessive or lacking vegetative cover on embankment East Ash Pond slope erosion on berms or embankments East Ash Pond debris on embankments/berms East Ash Pond detrioration, malfunctions or improper operation of overtopping control system East Ash Pond seepage from or through embankment West Ash Pond seepage from or through embankment (Copy) Visible damage to the pond liner is water level below damage Na 06/08/2024 06:48:44 CDT Reduced water level NA 06/08/2024 06:48:44 CDT Shift Supervisor notified NA 06/08/2024 06:48:44 CDT

Federal CCR Evaluations	West Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/08/2024 06:50:47 CDT
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	06/08/2024 06:50:49 CDT
Federal CCR Evaluations	West Ash Pond cracking on embankments/berms	No	06/08/2024 06:50:50 CDT
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	06/08/2024 06:50:53 CDT
Federal CCR Evaluations	West Ash Pond excessive or lacking vegetative cover on embankments	Yes	06/08/2024 06:51:11 CDT Excessive vegetation on south berm.
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	06/08/2024 06:51:23 CDT
Federal CCR Evaluations	West Ash Pond debris on embankments/berms	No	06/08/2024 06:51:20 CDT
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	06/08/2024 06:48:44 CDT
Federal CCR Evaluations	West Ash Pond visible releases	No	06/08/2024 06:51:17 CDT
West Ash Pond	Visible damage to the pond liner	No	06/08/2024 06:51:38 CDT
West Ash Pond Visible damage to the pond liner	Is water level below damage	NA	06/08/2024 06:48:44 CDT
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	06/08/2024 06:48:44 CDT
West Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/08/2024 06:48:44 CDT
West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/08/2024 06:48:44 CDT
West Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/08/2024 06:48:44 CDT

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 11245481

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 06/10/2024 10:02:13.110 CDT

Log Entry Date / Time: 06/10/2024 10:02 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

Group	<u>Title</u>	Value	Timestamp	Note
East Ash Pond	General Condition	Empty	06/10/2024 09:59:53 CDT	
East Ash Pond	Water Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	1.1	06/10/2024 10:00:05 CDT	OOS
East Ash Pond	Is ash being removed	No	06/10/2024 10:00:09 CDT	
East Ash Pond	In Service	No	06/10/2024 10:00:12 CDT	
West Ash Pond	General Condition	Empty	06/10/2024 10:00:17 CDT	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0.54	06/10/2024 10:00:22 CDT	
West Ash Pond	Is ash being removed	No	06/10/2024 10:00:25 CDT	
West Ash Pond	In Service	No	06/10/2024 10:00:27 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	06/10/2024 10:00:32 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	oos	06/10/2024 10:00:34 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	06/10/2024 10:00:37 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	06/10/2024 10:00:48 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/10/2024 10:00:50 CDT	

Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	06/10/2024 10:00:53 CDT
Federal CCR Evaluations	East Ash Pond cracking on embankments/berms	No	06/10/2024 10:00:55 CDT
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	06/10/2024 10:00:58 CDT
Federal CCR Evaluations	East Ash Pond excessive or lacking vegetative cover on embankment	No	06/10/2024 10:01:01 CDT
Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	06/10/2024 10:01:04 CDT
Federal CCR Evaluations	East Ash Pond debris on embankments/berms	No	06/10/2024 10:01:06 CDT
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	06/10/2024 09:59:11 CDT
Federal CCR Evaluations	East Ash Pond visible releases	No	06/10/2024 10:01:08 CDT
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	06/10/2024 10:01:12 CDT
East Ash Pond	Visible damage to the pond liner	No	06/10/2024 10:01:47 CDT
East Ash Pond Visible damage to the pond liner	is water level below damage	NA	06/10/2024 09:59:11 CDT
East Ash Pond Visible damage to the pond liner is water level below damage	Reduced water level	NA	06/10/2024 09:59:11 CDT
East Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/10/2024 09:59:11 CDT
East Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/10/2024 09:59:12 CDT

East Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/10/2024 09:59:12 CDT
Federal CCR Evaluations	West Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/10/2024 10:01:17 CDT
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	06/10/2024 10:01:20 CDT
Federal CCR Evaluations	West Ash Pond cracking on embankments/berms	No	06/10/2024 10:01:22 CDT
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	06/10/2024 10:01:26 CDT
Federal CCR Evaluations	West Ash Pond excessive or lacking vegetative cover on embankments	No	06/10/2024 10:01:31 CDT
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	06/10/2024 10:01:35 CDT
Federal CCR Evaluations	West Ash Pond debris on embankments/berms	No	06/10/2024 10:01:38 CDT
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	06/10/2024 09:59:11 CDT
Federal CCR Evaluations	West Ash Pond visible releases	No	06/10/2024 10:01:41 CDT
West Ash Pond	Visible damage to the pond liner	No	06/10/2024 10:01:51 CDT
West Ash Pond Visible damage to the pond liner	Is water level below damage	NA	06/10/2024 09:59:12 CDT
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	06/10/2024 09:59:12 CDT
West Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/10/2024 09:59:12 CDT

West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/10/2024 09:59:12 CDT
West Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/10/2024 09:59:12 CDT

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 11249411

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 06/12/2024 11:48:32.563 CDT

Log Entry Date / Time: 06/12/2024 11:48 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

Group	Title	Value	Timestamp	Note
East Ash Pond	General Condition		06/12/2024 11:42:29 CDT	
East Ash Pond	Water Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	1.1	06/12/2024 11:42:40 CDT	N
East Ash Pond	Is ash being removed	No	06/12/2024 11:42:53 CDT	
East Ash Pond	In Service	No	06/12/2024 11:42:58 CDT	
West Ash Pond	General Condition	Empty	06/12/2024 11:43:11 CDT	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0.54	06/12/2024 11:43:14 CDT	
West Ash Pond	Is ash being removed	No	06/12/2024 11:43:18 CDT	
West Ash Pond	In Service	No	06/12/2024 11:43:20 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	OOS	06/12/2024 11:43:37 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	oos	06/12/2024 11:43:47 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	06/12/2024 11:43:49 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	06/12/2024 11:44:04 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/12/2024 11:44:07 CDT	

Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	06/12/2024 11:44:09 CDT
Federal CCR Evaluations	East Ash Pond cracking on embankments/berms	No	06/12/2024 11:44:12 CDT
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	06/12/2024 11:44:14 CDT
Federal CCR Evaluations	East Ash Pond excessive or lacking vegetative cover on embankment	No	06/12/2024 11:44:16 CDT
Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	06/12/2024 11:44:31 CDT
Federal CCR Evaluations	East Ash Pond debris on embankments/berms	No	06/12/2024 11:44:37 CDT
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	06/12/2024 11:42:19 CDT
Federal CCR Evaluations	East Ash Pond visible releases	No	06/12/2024 11:44:41 CDT
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	06/12/2024 11:44:44 CDT
East Ash Pond	Visible damage to the pond liner	No	06/12/2024 11:48:00 CDT
East Ash Pond Visible damage to the pond liner	is water level below damage	NA	06/12/2024 11:42:20 CDT
East Ash Pond Visible damage to the pond liner is water level below damage	Reduced water level	NA	06/12/2024 11:42:20 CDT
East Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/12/2024 11:42:20 CDT
East Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/12/2024 11:42:20 CDT

East Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/12/2024 11:42:20 CDT
Federal CCR Evaluations	West Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/12/2024 11:44:52 CDT
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	06/12/2024 11:44:56 CDT
Federal CCR Evaluations	West Ash Pond cracking on embankments/berms	No	06/12/2024 11:45:00 CDT
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	06/12/2024 11:45:08 CDT
Federal CCR Evaluations	West Ash Pond excessive or lacking vegetative cover on embankments	No	06/12/2024 11:45:16 CDT
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	06/12/2024 11:45:20 CDT
Federal CCR Evaluations	West Ash Pond debris on embankments/berms	No	06/12/2024 11:45:24 CDT
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	06/12/2024 11:42:20 CDT
Federal CCR Evaluations	West Ash Pond visible releases	No	06/12/2024 11:47:23 CDT
West Ash Pond	Visible damage to the pond liner	No	06/12/2024 11:48:10 CDT
West Ash Pond Visible damage to the pond liner	Is water level below damage	NA	06/12/2024 11:42:20 CDT
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	06/12/2024 11:42:20 CDT
West Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/12/2024 11:42:20 CDT

West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/12/2024 11:42:20 CDT	
West Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/12/2024 11:42:20 CDT	

Round: Ash Pond Inspection | Ash Pond Inspection

Entry ID: 11253952

Logbook Origination: Waukegan Rounds

Created By:

System Timestamp: 06/14/2024 13:29:46.340 CDT

Log Entry Date / Time: 06/14/2024 13:29 CDT **Category:** Ash Pond Inspection | Ash Pond Inspection

Event / Action: Complete

<u>Group</u>	<u>Title</u>	Value	Timestamp	<u>Note</u>
East Ash Pond	General Condition	Full	06/14/2024 13:26:26 CDT	
East Ash Pond	Water Level in Pond(At 12 increase flow to clarifier, at 5 decrease flow)	1.02	06/14/2024 13:27:04 CDT	Ash pond no longer in service.
East Ash Pond	Is ash being removed	No	06/14/2024 13:27:07 CDT	
East Ash Pond	In Service	No	06/14/2024 13:27:09 CDT	
West Ash Pond	General Condition	Empty	06/14/2024 13:27:14 CDT	
West Ash Pond	Water level in Pond(At 12 increase flow to clarifier)	0	06/14/2024 13:27:17 CDT	
West Ash Pond	Is ash being removed	No	06/14/2024 13:27:19 CDT	
West Ash Pond	In Service	No	06/14/2024 13:27:21 CDT	
Instrumentation Checks	A Sluice Return Pump in good condition	oos	06/14/2024 13:27:25 CDT	
Instrumentation Checks	B Sluice Return Pump in good condition	OOS	06/14/2024 13:27:27 CDT	
Instrumentation Checks	C Sluice Return Pump in good condition	OOS	06/14/2024 13:27:29 CDT	
Federal CCR Evaluations	East Ash Pond seepage from or through embankment	No	06/14/2024 13:27:32 CDT	
Federal CCR Evaluations	East Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/14/2024 13:27:34 CDT	

Federal CCR Evaluations	East Ash Pond signs of piping/channels or other internal erosion on embankments	No	06/14/2024 13:27:36 CDT
Federal CCR Evaluations	East Ash Pond cracking on embankments/berms	No	06/14/2024 13:27:37 CDT
Federal CCR Evaluations	East Ash Pond animal burrows on embankments	No	06/14/2024 13:27:40 CDT
Federal CCR Evaluations	East Ash Pond excessive or lacking vegetative cover on embankment	Yes	06/14/2024 13:27:46 CDT Excessive vegetation
Federal CCR Evaluations	East Ash Pond slope erosion on berms or embankments	No	06/14/2024 13:27:50 CDT
Federal CCR Evaluations	East Ash Pond debris on embankments/berms	No	06/14/2024 13:27:52 CDT
Federal CCR Evaluations	East Ash Pond detrioration, malfunctions or improper operation of overtopping control system	N/A	06/14/2024 13:26:10 CDT
Federal CCR Evaluations	East Ash Pond visible releases	No	06/14/2024 13:28:00 CDT
Federal CCR Evaluations	West Ash Pond seepage from or through embankment (Copy)	No	06/14/2024 13:28:02 CDT
East Ash Pond	Visible damage to the pond liner	No	06/14/2024 13:28:34 CDT
East Ash Pond Visible damage to the pond liner	is water level below damage	NA	06/14/2024 13:26:11 CDT
East Ash Pond Visible damage to the pond liner is water level below damage	Reduced water level	NA	06/14/2024 13:26:11 CDT
East Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/14/2024 13:26:11 CDT
East Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/14/2024 13:26:11 CDT

East Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/14/2024 13:26:11 CDT
Federal CCR Evaluations	West Ash Pond sinkholes/depressions/bulges in pond or embankments	No	06/14/2024 13:28:04 CDT
Federal CCR Evaluations	West Ash Pond signs of piping/channels or other internal erosion on embankment	No	06/14/2024 13:28:05 CDT
Federal CCR Evaluations	West Ash Pond cracking on embankments/berms	No	06/14/2024 13:28:07 CDT
Federal CCR Evaluations	West Ash Pond animal burrows on embankment	No	06/14/2024 13:28:09 CDT
Federal CCR Evaluations	West Ash Pond excessive or lacking vegetative cover on embankments	Yes	06/14/2024 13:28:14 CDT
Federal CCR Evaluations	West Ash Pond slope erosion on berms or embankments	No	06/14/2024 13:28:17 CDT
Federal CCR Evaluations	West Ash Pond debris on embankments/berms	No	06/14/2024 13:28:19 CDT
Federal CCR Evaluations	West Ash Pond deterioration, malfunctions or improper operation of overtopping control systems	N/A	06/14/2024 13:26:11 CDT
Federal CCR Evaluations	West Ash Pond visible releases	No	06/14/2024 13:28:22 CDT
West Ash Pond	Visible damage to the pond liner	No	06/14/2024 13:28:37 CDT
West Ash Pond Visible damage to the pond liner	Is water level below damage	NA	06/14/2024 13:26:11 CDT
West Ash Pond Visible damage to the pond liner Is water level below damage	Reduced water level	NA	06/14/2024 13:26:11 CDT
West Ash Pond Visible damage to the pond liner	Describe location and size	NA	06/14/2024 13:26:11 CDT

West Ash Pond Visible damage to the pond liner	Shift Supervisor notified	NA	06/14/2024 13:26:11 CDT	
West Ash Pond Visible damage to the pond liner	Station Management notified	NA	06/14/2024 13:26:11 CDT	