



MEMORANDUM

DATE: December 17, 2019

TO: **Mr. Richard Gray**
Environmental Specialist
NRG Energy Services
Plum Point Energy Station

FROM: **Jason J Ghidotti, PE** 
FTN Associates, Ltd.

SUBJECT: 2019 Annual Inspection of CCR Dust Control System for PPES CCR Landfill
FTN No. 14590-2005-001

FTN Associates, Ltd. (FTN) has been contracted by Plum Point Services Company, LLC (PPSC) to prepare the 2019 annual Coal Combustion Residue (CCR) fugitive dust control report for the Plum Point Energy Station (PPES) CCR Landfill (Landfill) located in Osceola, AR. This technical memorandum provides a summary of the assessment of the PPES plant fugitive dust control system from December 2018 to December 2019 and findings from an inspection by FTN on December 12, 2019.

In accordance with §257.80(c), the purpose of the report is to provide a summary of the:

1. Actions taken by the Owner or Operator to control CCR fugitive dust,
2. Citizen complaints regarding fugitive dust, and
3. Any corrective measures taken during the reporting period.

The PPES facility has a fugitive dust control plan (FTN, October 2015) that provides information on potential sources of dust; fugitive dust control measures; methods for inspection, monitoring, and recordkeeping; and, periodic assessment of the plan. A copy of the plan is kept in the office of the PPES Environmental Manager and the offices of the PPES CCR management company, Boral Resources (Boral). Boral replaced Charah as the PPES CCR management company in early 2019.

Fugitive Dust Control Measures

NRG Energy Services (NRG), the power plant and Boral manage fugitive dust at the PPES power plant and the Landfill in accordance with the CCR Fugitive Dust Control Plan (FTN, October 2015). These measures include:

1. Adhering to the speed limit posted on the haul road from the CCR loading station at the plant to the active disposal area.
2. Using adequate water to blend into the CCR materials in the pug mill to minimize fugitive dust during truck loading operations, but not too much to create excess free liquids.
3. Using a street sweeper with water spraying capability on the paved portion of the haul road at least once per shift. The frequency of sweeping/wetting activities is increased (drier conditions) or decreased (rain or snow) depending on the weather.
4. Applying water on the gravel portion of the haul road. Water is applied at a sufficient rate to control dust, but not to create excessive runoff. Water is applied more frequently in drier or windy conditions.
5. Cleaning out haul truck beds in the active disposal area on an as-needed basis to remove materials left in the truck bed.
6. Wetting ancillary gravel roads not used to haul ash material on an as-needed basis.
7. Wetting CCR material in the active disposal area if the material becomes too dry before grading of the waste.

Boral inspects the CCR loading area and the haul road at least twice daily and keeps records of the sweeping and wetting operations. Copies of the records are included in Attachment 1. In addition, Boral performs the weekly inspection of the Landfill, which includes assessing the condition of the CCR disposal and grading operations. Copies of these inspections during the reporting period are included in Attachment 2.

An inspection by FTN on December 12, 2019 along with an interview of the Landfill Manager confirmed usage of the fugitive dust control measures listed above. Attachment 3 provides photos of the landfill taken during the inspection.

Citizen Complaints During the Reporting Period

There were no citizen complaints about fugitive dust from the PPES plant or the Landfill during the reporting period.

Corrective Measures Taken During the Reporting Period

There were no corrective measures implemented by NRG or Boral during the reporting period.

cc: Eddie Wamble, Boral PPES Landfill Manager

ATTACHMENT 1

Logs of Sweeping and Wetting of CCR Haul Road

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: Jan Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed	Currently Raining? (Y/N)					
1	AM:												
	PM:												
2	AM: 11:30	EW	HR	Y	41°	D	N-5	N	N	Y	N	N	
	PM: 1:32	EW	LF	Y	38°	D	N-5	N	N	Y	N	N	
3	AM: 9:00	EW	HR	Y	39°	D	N-5	N	N	Y	N	N	
	PM: 12:22	EW	HR	Y	42°	D	NE-3	N	N	Y	N	N	
4	AM: 9:25	EW	LF	Y	42°	W	SW-4	Y	N	N	N	N	
	PM: 12:15	EW	LF	Y	41°	W	SW-1	Y	Y	N	N	N	
5	AM:												
	PM:												
6	AM:												
	PM:												
7	AM: 7:09	EW	HR	Y	59°	W	SW-9	N	N	N	N	N	
	PM: 1:50	EW	LF	Y	61°	W	W-4	N	N	N	N	N	
8	AM: 10:30	EW	HR	Y	61°	D	NW-12	N	N	Yes	N	N	
	PM: 12:10	EW	LF	Y	63°	D	NW-14	N	N	Yes	N	N	
9	AM: 11:00	BB	LF	Yes	46°	D	NW-12	N	N	Yes	N	N	
	PM: 12:30	BB	HR	Yes	48°	D	N-12	N	N	Y	N	N	
10	AM: 7:34	EW	HR	Y	30°	D	N-8	N	N	N	N	N	
	PM: 3:30	EW	HR	Y	41°	D	N-6	N	N	Y	N	N	
11	AM: 9:30	EW	LF	N	36°	D	NE-7	N	N	Y	N	N	
	PM: 11:00	DS	LF	Y	43°	D	N-4	N	N	Y	N	N	
12	AM:												
	PM:												
13	AM:												
	PM:												
14	AM: 1:00	D.S.	LF	Y	43°	D	N-1	N	N	Y	N	N	
	PM: 3:09	D.S.	HR	Y	39°	D	N-0	N	N	Y	N	N	
15	AM: 7:45	D.S.	LF	Yes	39°	D	SW-6	N	N	Yes	NO	NO	
	PM: 2:30	D.S.	HR	Yes	44°	Dry	SW-8	NO	NO	Yes	NO	NO	
16	AM: 10:30	D.S.	HR	Yes	39°	Dry	SW-5	NO	NO	Yes	NO	NO	
	PM: 2:00	D.S.	LF	Yes	48°	Dry	S-6	NO	NO	Yes	NO	NO	

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions			Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments	
					Temperature	Dry/Wet/Humid	Wind Conditions						Currently Raining?
17	AM: 10:00	DS	HR	Y	45°	D	S-4	N	N	Y	2	N	
	PM: 1:40	DS	HR	Y	53	D	S-4	N	N	Y	2	N	
18	AM: 11:00	EW	LF	Y	47°	D	E-6	N	N	Y	2	N	
	PM: 1:28	EW	HR	Y	50°	D	SE-6	N	N	Y	2	N	
19	AM:												
	PM:												
20	AM:												
	PM:												
21	AM: 11:00	D.S	HR	Y	31°	Dry	SE-11	N	N	N Freezing	N	N	
	PM: 2:30	DS	LF	Y	36°	Wet	SE-11	N	N	Y	N	N	
22	AM: 11:30	EW	HR	Y	44°	D	SE-14	N	N	Y	N	N	
	PM: 1:00	EW	LF	Y	46°	D	SE-14	N	N	Y	N	N	
23	AM: 10:30	D.S	LF	Y	39°	Wet	NW-12	Yes	N	N	NO	NO	
	PM: 2:30	DS	HR	Y	36°	Wet	NW-12	Yes	N	N	NO	NO	
24	AM: 11:30	EW	HR	N	39°	Wet	SW-7	N	N	N	N	N	
	PM: 3:00	EW	HR	N	43°	Wet	SW-7	N	N	N	N	N	
25	AM: 11:30	EW	LF	N	30°	D	NE-2	N	N	N	N	N	
	PM:												
26	AM:												
	PM:												
27	AM:												
	PM: 7:00	DS	LF	Yes	48°								
28	AM: 10:30	D.S	LF	Yes	48°	Dry	SW-10	N	N	Y	N	N	
	PM: 3:00	D.S	HR	Yes	56°	Dry	SW-10	N	N	Y	N	N	
29	AM: 9:30	D.S	HR	Y	25°	Dry	NW-11	N	NO	N Freezing	N	N	
	PM: 2:45	D.S	LF	Y	34°	Dry	SW-8	N	N	N Free	N	N	
30	AM: 9:30	D.S	LF	Y	23°	Dry	N-12	N	N	Freezing	N	N	
	PM: 2:30	D.S	HR	Y	26°	Dry	N-7	N	N	Freezing	N	N	
31	AM: 10:15	D.S	LF	Yes	30°	Dry	E-8	N	NO	Freezing	N	N	
	PM: 2:30	D.S	HR	Yes	43°	Dry	S-6	N	NO	Y	N	N	

10:30 -

Month: April Year: 2019

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed	Currently Raining? (Y/N)					
1	AM: 8:30	EW	LF	Y	36°	D	N-8	N	N	Y	N	N	
	PM: 12:01	EW	HR	Y	62°	D	N-9	N	N	Y	N	N	
2	AM: 11:30	EW	LF	Y	61°	D	S-10	N	N	Y	N	N	
	PM: 2:30	EW	HR	Y	73°	D	SW-8	N	N	Y	N	N	
3	AM: 9:00	EW	HR	Y	65°	D	SE-9	N	N	Y	N	N	
	PM: 1:00	EW	LF	Y	75°	D	S-8	N	N	Y	N	N	
4	AM: 11:00	EW	HR	Y	51°	W	S-9	Y	N	N	N	N	
	PM: 2:30	EW	HR	Y	55°	W	SE-9	Y	N	N	N	N	
5	AM: 10:30	EW	HR	Y	49°	D	S-7	N	N	Y	N	N	
	PM: 1:10	EW	LF	Y	52°	D	SW-4	N	N	Y	N	N	
6	AM:												
6	PM:												
7	AM:												
7	PM:												
8	AM: 8:00	EW	HR	Y	61°	D	S-4	N	N	N	N	N	Plant in outage
	PM: 2:30	EW	LF	Y	78°	D	S-3	N	N	N	N	N	Plant in outage
9	AM: 8:10	EW	LF	N	79°	D	SE-4	N	N	N	N	N	Plant in outage
	PM: 2:45	EW	LF	N	70°	D	S-4	N	N	N	N	N	
10	AM: 8:00	EW	HR	N	69°	D	SE-4	N	N	N	N	N	
	PM: 4:00	EW	LF	N	81°	D	S-18	N	N	N	N	N	Plant in outage
11	AM: 8:30	EW	LF	N	69°	D	S-9	N	N	N	N	N	
	PM: 4:00	EW	LF	N	80°	D	S-18	N	N	N	N	N	Plant in outage
12	AM: 8:00	EW	LF	N	72°	D	S-10	N	N	N	N	N	Plant in outage
	PM: 3:00	EW	HR	N	81°	D	S-10	N	N	N	N	N	Plant in outage
13	AM:												
13	PM:												
14	AM:												
14	PM:												
15	AM: 11:30	EW	HR	N	61	D	SE-5	N	N	N	N	N	Plant in outage
	PM: 2:35	EW	HR	N	66	D	S-6	N	N	N	N	N	Plant in outage
16	AM: 11:30	EW	LF	N	64	D	S-5	N	N	N	N	N	Plant in outage
	PM: 2:00	EW	LF	N	68	D	S-4	N	N	N	N	N	Plant in outage

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/	Currently Raining?					
17	AM: 10:00	EW	HR	N	66°	D	S-4	N	N	N	N		
	PM: 12:45	EW	HR	N	69°	D	S-2	N	N	N	N		
18	AM: 9:30	EW	LF	N	68°	D	S-6	N	N	N	N		
	PM: 12:00	EW	LF	N	74°	D	S-0	N	N	N	N		
19	AM: 11:30	EW	LF	N	72°	D	SE-8	N	N	N	N		
	PM: 12:00	EW	HR	N	74°	D	SE-5	N	N	N	N		
20	AM:												
	PM:												
21	AM:												
	PM:												
22	AM:												
	PM:												
23	AM: 11:00	EW	HR	N	75°	D	S-9	N	N	N	N		
	PM: 3:00	EW	LF	N	77°	D	S-9	N	N	N	N		
24	AM: 10:15	EW	HR	N	76°	D	S-7	N	N	N	N		
	PM: 12:15	EW	LF	N	78°	D	S-6	N	N	N	N		
25	AM: 11:00	EW	HR	N	78°	D	SE-2	N	N	N	N		
	PM: 12:00	EW	HR	N	80°	D	SE-4	N	N	N	N		
26	AM: 9:00	EW	LF	N	72°	D	S-0	N	N	N	N		
	PM: 1:15	EW	LF	N	82°	D	S-10	N	N	N	N		
27	AM:												
	PM:												
28	AM:												
	PM:												
29	AM: 9:10	EW	HR	N	61°	D	N-2	N	N	N	N		
	PM: 2:40	EW	HR	N	82°	D	N-2	N	N	N	N		
30	AM: 7:30	EW	HR	N	48°	D	N-1	N	N	N	N		
	PM: 3:45	EW	LF	N	84°	D	N-1	N	N	N	N		
31	AM:												
	PM:												

Q/A 2
 19
 DUSTAGE

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: May Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed	Currently Raining? (Y/N)					
1	AM: 11:00	EW	LF	N	72°	W	S-10	Y	N	N	N	N	Plant in Outage
	PM: 2:30	EW	HR	N	72°	W	S-12	Y	N	N	N	N	
2	AM: 8:04	EW	HR	N	72°	D	S-6	N	N	N	N	N	
	PM: 12:15	EW	LF	N	76°	D	S-4	N	N	N	N	N	
3	AM: 11:00	EW	LF	N	74	W	NE-3	N	N	N	N	N	
	PM: 2:35	EW	HR	N	78°	W	NE-3	N	N	N	N	N	
4	AM:												
	PM:												
5	AM:												
	PM:												
6	AM: 11:50	EW	HR	N	75°	D	S-3	N	N	N	N	N	Plant in Outage
	PM: 1:55	EW	LF	N	75°	D	S-3	N	N	N	N	N	
7	AM: 11:00	PP	LF	N	78°	D	SW-2	N	N	N	N	N	
	PM: 1:50	PP	LF	N	81°	D	S-2	N	N	N	N	N	
8	AM: 11:15	EW	LF	N	80°	D	S-12	N	N	N	N	N	
	PM: 3:30	EW	LF	N	84°	D	S-14	N	N	N	N	N	Plant in Outage
9	AM: 8:00	EW	LF	N	66°	W	S-10	Y	N	N	N	N	
	PM: 2:00	EW	HR	N	72°	W	S-E-8	N	N	N	N	N	
10	AM: 8:12	EW	HR	N	55°	D	N-10	N	N	N	N	N	
	PM: 1:00	EW	HR	N	70°	D	N-4	N	N	N	N	N	
11	AM: 8:00	EW	LF	N	72°	W	S-10	Y	N	N	N	N	
	PM:												
12	AM:												
	PM:												
13	AM: 9:00	PP	LF	N	58°	D	NE-8	N	N	N	N	N	
	PM: 1:30	PP	HR	N	70°	D	N-7	N	N	Yes	N	N	
14	AM: 7:20	EW	HR	Y	55°	D	NE-1	N	N	Yes	N	N	
	PM: 12:55	EW	HR	Y	70°	D	NE-1	N	N	Yes	N	N	
15	AM: 10:30	EW	HR	Y	75°	D	NW-7	N	N	Yes	N	N	
	PM: 1:20	EW	HR	Y	81	D	N-2	N	N	Yes	N	N	
16	AM: 11:30	EW	LF	Y	80	D	NE-2	N	N	Yes	N	N	
	PM: 1:00	EW	HR	Y	81	D	S-1	N	N	Yes	N	N	

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions	Currently Raining?					
17	AM: 11:00	EW	HR	Y	77°	D	S-3	N	N	Yes	N	N	
	PM: 1:00	PP	LF	Y	83°	D	SW-3	N	N	Y	N	N	
18	AM:												
	PM:												
19	AM:												
	PM:												
20	AM: 11:45	EW	HR	Y	79°	D	N-2	N	N	Yes	N	N	
	PM: 2:00	EW	HR	Y	89°	D	N-5	N	N	Yes	N	N	
21	AM: 10:30	EW	HR	Y	79°	D	S-14	N	N	Yes	N	N	
	PM: 1:36	EW	HR	Y	84°	D	S-16	W	N	Yes	N	N	
22	AM: 11:45	EW	LF	Y	77°	D	S-14	N	N	Yes	N	N	
	PM: 3:30	EW	HR	Y	86°	D	S-12	N	N	Yes	N	N	
23	AM: 9:00	EW	LF	Y	80°	D	S-4	N	N	Yes	N	N	
	PM: 3:30	EW	LF	Y	90°	D	S-2	N	N	Yes	N	N	
24	AM: 9:18	EW	HR	Y	84°	D	S-1	N	N	Yes	N	N	
	PM: 3:20	EW	LF	Y	91°	D	S-4	N	N	Yes	N	N	
25	AM: 9:00	EW	HR	Y	82°	D	S-4	N	N	Yes	N	N	
	PM: 2:30	EW	HR	Y	88°	D	S-4	N	N	Yes	N	N	
26	AM:												
	PM:												
27	AM:												
	PM:												
28	AM: 11:00	EW	HR	Y	85°	D	S-4	N	N	Yes	N	N	
	PM: 1:15	EW	HR	Y	88°	D	S-4	N	N	Yes	N	N	
29	AM: 11:11	EW	HR	Y	84°	D	S-4	N	N	Yes	N	N	
	PM: 1:30	EW	LF	Y	85°	D	SW-3	N	N	Yes	N	N	
30	AM: 11:20	EW	HR	Y	77°	D	SW-3	N	N	Yes	N	N	
	PM: 1:30	EW	LF	Y	86°	D	SW-3	N	N	Yes	N	N	
31	AM: 10:00	EW	HR	Y	81°	D	SW-3	N	N	Yes	N	N	
	PM: 3:00	EW	LF	Y	90°	D	S-4	N	N	Yes	N	N	

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: July Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/ Humid	Wind Conditions/ Speed	Currently Raining? (Y/N)					
1	AM: 8:00	EW	HR	Yes	80°	D	SW-0	N	N	Yes	NO	NO	
	PM: 1:00	EW	LF	Yes	95°	D	S-2	N	N	Yes	NO	NO	
2	AM: 9:00	EW	HR	Yes	85	D	S-0	N	N	Yes	NO	NO	
	PM: 4:00	EW	HR	Yes	92	D	SW-3	N	N	Yes	NO	NO	
3	AM: 11:00	EW	LF	Yes	93	D	SW-1	N	N	Yes	NO	NO	
	PM: 2:00	EW	HR	Yes	95°	D	SW-0	N	N	Yes	NO	NO	
4	AM: 8:00	EW											
	PM:												
5	AM: 11:00	EW	HR	Yes	93°	D	S-1	N	N	Yes	NO	NO	
	PM: 2:00	EW	LF	Yes	98°	D	SW-0	N	N	Yes	NO	NO	
6	AM:												
	PM:												
7	AM:												
	PM:												
8	AM: 8:00	EW	HR	Y	81	D	N-0	N	2	Yes	2	2	
	PM: 1:00	EW	LF	Y	100°	D	NE-1	N	2	Yes	2	2	
9	AM: 9:00	EW	HR	Y	86°	D	N-0	2	2	Yes	2	2	
	PM: 1:00	EW	LF	Y	97°	D	N-0	2	2	Yes	2	2	
10	AM: 8:05	EW	HR	Y	84°	D	N-0	2	2	Yes	2	2	
	PM: 12:24	EW	HR	Y	94°	D	S-2	2	2	Yes	2	2	
11	AM: 9:00	EW	HR	Y	80°	D	N-0	2	2	Yes	2	2	
	PM: 3:00	EW	LF	Y	93°	D	N-2	2	2	Yes	2	2	
12	AM: 10:30	EW	HR	Y	86°	D	NE-3	2	2	Yes	2	2	
	PM: 1:00	EW	LF	Y	86°	D	N-3	2	2	Yes	2	2	
13	AM: 8:15	EW	HR	Y	72°	W	SE-5	Y	2	Yes	2	2	
	PM: 8:00	EW											
14	AM: 1:00	EW	HR	Y	74°								
	PM:												
15	AM: 11:00	EW	HR	Y	74°	W	SE-2	Y	2	Yes	2	2	
	PM: 12:30	EW	LF	Y	74°	W	SE-2	Y	2	Yes	2	2	
16	AM: 8:00	EW	HR	Y	75°	W	SW-1	Y	2	Yes	2	2	
	PM: 6:00	EW	LF	Y	77°	W	SW-3	N	2	Yes	2	2	

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/ Humid	Wind Conditions	Currently Raining?					
17	AM: 8:00	EW	LF	Y	79°	D	SW-0	N	N	Y	N	N	
	PM: 2:00	EW	HR	Y	98°	D	SW-0	N	N	Y	N	N	
18	AM: 7:51	EW	HR	Y	79°	D	SW-1	N	N	Y	N	N	
	PM: 2:00	EW	HR	Y	97°	D	S-3	N	N	Y	N	N	
19	AM: 9:00	EW	LF	Y	83°	D	SW-0	N	N	X	N	N	
	PM: 12:00	EW	HR	Y	99°	D	SW-4	N	N	Y	N	N	
20	AM:												
	PM:												
21	AM:												
	PM:												
22	AM: 11:30	EW	HR	Y	82°	D	NW-4	N	N	Y	N	N	
	PM: 12:42	EW	LF	Y	81°	W	NW-4	N	N	Y	N	N	
23	AM: 8:00	EW	HR	Y	71°	D	N-1	N	N	X	N	N	
	PM: 1:30	EW	LF	Y	81°	D	N-4	N	N	Y	N	N	
24	AM: 9:00	EW	HR	Y	72	D	N-2	N	N	Y	N	N	
	PM: 1:00	EW	LF	Y	85°	D	NE-1	N	N	Y	N	N	
25	AM: 10:00	EW	LF	Y	77	D	NE-0	N	N	Y	N	N	
	PM: 1:20	EW	HR	Y	87°	D	NE-0	N	N	Y	N	N	
26	AM:												
	PM:												
27	AM:												
	PM:												
28	AM:												
	PM:												
29	AM: 9:00	EW	HR	Y	75°	D	N-0	N	N	Y	N	N	
	PM: 2:00	EW	LF	Y	91°	D	N-4	N	N	Y	N	N	
30	AM: 8:00	EW	HR	Y	77°	D	NE-1	N	N	Y	N	N	
	PM: 3:00	EW	LF	Y	84°	D	NNE-0	N	N	Y	N	N	
31	AM: 11:00	EW	HR	N	86°	D	NW-4	N	N	Y	N	N	
	PM: 12:44	EW	LF	Y	86°	D	N-4	N	N	Y	N	N	

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: Aug Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions			Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed					
1	AM: 8:45	AW	LF	Y	78°	D	N-1	N	Y	N	N	
	PM: 1:00	AW	HR	Y	81°	D	N-1	N	Y	N	N	
2	AM: 9:00	EW	LF	Y	75°	D	N-0	N	Y	N	N	
	PM: 2:50	EW	HR	Y	88°	D	N-0	N	Y	N	N	
3	AM:											
	PM:											
4	AM:											
	PM:											
5	AM: 11:30	EW	HR	Y	84°	D	NE-3	N	Y	N	N	
	PM: 2:21	EW	LP	Y	89°	D	SE-0	N	Y	N	N	
6	AM: 10:00	EW	LF	Y	86°	D	S-4	N	Y	N	N	
	PM: 3:00	EW	HR	Y	97°	D	SW-2	N	Y	N	N	
7	AM: 8:00	EW	HR	Y	80°	D	S-0	N	Y	N	N	
	PM: 2:00	EW	HR	Y	98°	D	S-2	N	Y	N	N	
8	AM: 8:00	EW	LP	Y	75°	W	S-0	N	Y	N	N	
	PM: 3:30	EW	HR	Y	81°	D	S-2	N	Y	N	N	
9	AM: 9:00	EW	HR	Y	78°	D	SE-1	N	Y	N	N	
	PM: 3:00	EW	LF	Y	89°	D	S-0	N	Y	N	N	
10	AM:											
	PM:											
11	AM:											
	PM:											
12	AM: 9:30	EW	LF	Y	90°	D	S-2	N	Y	N	N	
	PM: 3:10	EW	HR	Y	99°	D	SSE-1	N	Y	N	N	
13	AM: 9:00	EW	LF	Y	87°	D	S-1	N	Y	N	N	
	PM: 3:00	EW	HR	Y	98°	D	SE-2	N	Y	N	N	
14	AM: 10:00	EW	LF	Y	85	D	N-0	N	Y	N	N	
	PM: 3:00	EW	HR	Y	94°	D	N-1	N	Y	N	N	
15	AM: 9:00	EW	LF	Y	77°	D	NW-2	N	Y	N	N	
	PM: 3:19	EW	HR	Y	93°	D	NW-0	N	Y	N	N	
16	AM: 11:30	EW	LF	Y	86°	D	SW-6	N	Y	N	N	
	PM: 2:22	EW	HR	Y	88°	D	SW-6	N	Y	N	N	

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions			Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/					
17	AM:											
	PM:											
18	AM:											
	PM:											
19	AM: 10:00	AW	LF	Y	84°	D	S-0	N	Y	Y	N	
	PM: 2:00	AW	HR	Y	101	D	S-2	N	Y	Y	N	
20	AM: 11:32	EW	HR	Y	93°	D	SE-4	N	Y	Y	N	
	PM: 1:40	EW	LF	Y	93°	D	SW-4	N	Y	Y	N	
21	AM: 11:00	EW	LF	Y	90°	D	S-1	N	Y	Y	N	
	PM: 2:57	EW	HR	Y	92°	D	SE-3	N	Y	Y	N	
22	AM: 10:00	EW	LF	Y	86	D	SW-4	N	Y	Y	N	
	PM: 2:23	EW	HR	Y	73°	W	SW-4	Y	N	Y	N	
23	AM: 11:00	EW	LF	Y	75°	D	SW-2	N	Y	Y	N	
	PM: 2:00	EW	HR	Y	77°	D	S-1	N	Y	Y	N	
24	AM:											
	PM:											
25	AM:											
	PM:											
26	AM: 10:15	EW	LF	Y	79°	D	SE-0	N	Y	Y	N	
	PM: 2:00	EW	HR	Y	86°	D	SE-1	N	Y	Y	N	
27	AM: 11:30	EW	LF	Y	82°	D	S-1	N	Y	Y	N	
	PM: 1:00	EW	HR	Y	85°	D	SW-2	N	Y	Y	N	
28	AM: 11:00	EW	LF	Y	81°	D	S-0	NO	NO	YES	NO	
	PM: 2:15	EW	HR	Y	88°	D	SW-2	NO	NO	YES	NO	
29	AM: 11:15	EW	LF	Y	85	D	S-1	NO	NO	YES	NO	
	PM: 2:00	EW	HR	Y	92°	D	SE-2	NO	YES	YES	NO	
30	AM: 11:00	EW	LF	Y	86°	D	SE-0	NO	YES	YES	NO	
	PM: 5:20	EW	HR	Y	88°	D	S-0	NO	NO	YES	NO	
31	AM: 11:00	EW	HR	Y	90	D	N-0	NO	NO	YES	NO	
	PM: 1:30	EW	LF	Y	95	D	NO	NO	YES	YES	NO	

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: Sep Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions				Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed	Currently Raining? (Y/N)					
1	AM: 8:15	EW	LF	Y	72°	D	NE-6	N	N	Y	N	N	
	PM:												
2	AM: 9:00	EW	HR	Y	77°	D	NW-1	N	N	Y	N	N	
	PM: 2:00	EW	HR	Y	88°	D	N-2	N	N	Y	N	N	
3	AM: 9:20	EW	LF	Y	79°	D	NW-0	N	N	Y	N	N	
	PM: 2:10	EW	HR	Y	97°	D	N-0	N	N	Y	N	N	
4	AM: 8:00	EW	LF	Y	74°	D	NW-0	N	N	Y	N	N	
	PM: 1:00	EW	HR	Y	99°	D	NW-0	N	Y	Y	N	N	
5	AM: 10:00	EW	LF	Y	79°	D	N-1	N	Y	Y	N	N	
	PM: 2:00	EW	HR	Y	89°	D	N-0	N	N	Y	N	N	
6	AM: 8:30	EW	HR	Y	73°	D	NW-4	N	N	Y	N	N	
	PM:												
7	AM:												
	PM:												
8	AM:												
	PM:												
9	AM: 9:00	EW	HR	Y	81°	D	S-0	N	Y	Y	N	N	
	PM: 3:00	EW	LF	Y	99°	D	S-1	N	N	Y	N	N	
10	AM: 9:00	EW	HR	Y	78°	D	S-0	N	N	Y	N	N	
	PM: 3:00	EW	LF	Y	90°	D	SW-2	N	N	Y	N	N	
11	AM: 8:00	EW	HR	Y	78°	D	SW-4	N	N	Y	N	N	
	PM: 3:45	EW	HR	Y	93°	D	SW-8	N	N	Y	N	N	
12	AM: 11:00	EW	LF	Y	91°	D	SW-4	N	N	Y	N	N	
	PM: 1:30	EW	HR	Y	93°	D	SW-4	N	N	Y	N	N	
13	AM:												
	PM:												
14	AM:												
	PM:												
15	AM:												
	PM:												
16	AM: 11:40	EW	HR	Y	95°	D	N-4	N	N	Y	N	N	
	PM: 1:14	EW	LF	Y	101°	D	N-4	N	N	Y	N	N	

PPES FACILITY CCR DUST CONTROL MONITORING WORKSHEET

Month: Oct Year: 2019

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions			Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Speed					
1	AM: 11:30	EW	HR	Y	91°	D	S-3	N	N	Y	2	2
	PM: 5:00	EW	LF	Y	94°	D	SE-3	N	N	Y	2	2
2	AM: 11:00	EW	LF	Y	92°	D	SE-2	N	N	Y	2	2
	PM: 3:00	EW	HR	Y	96°	D	SE-4	N	N	Y	2	2
3	AM: 8:00	EW	HR	Y	73	D	SW-1	N	N	Y	2	2
	PM: 12:45	EW	LF	Y	92°	D	SE-3	N	N	Y	2	2
4	AM: 11:00	EW	LF	Y	77°	D	NE-9	N	N	Y	2	2
	PM: 5:00	EW	HR	Y	79°	D	NE-9	N	N	Y	2	2
5	AM:											
	PM:											
6	AM:											
	PM:											
7	AM: 10:51	EW	HR	Y	60°	W	NE-9	N	N	Y	2	2
	PM: 3:00	EW	LF	Y	68°	D	NE-9	N	N	Y	2	2
8	AM: 10:10	EW	HR	Y	62°	D	NE-8	N	N	Y	2	2
	PM: 1:05	EW	LF	Y	69°	D	NE-8	N	N	Y	2	2
9	AM: 10:20	EW	HR	Y	69°	D	NE-6	N	N	Y	2	2
	PM: 3:00	EW	LF	Y	80°	D	N-6	N	N	Y	2	2
10	AM: 10:00	EW	HR	Y	74°	D	N-1	N	N	Y	2	2
	PM: 3:00	EW	LF	Y	86°	D	NE-2	N	N	Y	2	2
11	AM: 9:40	EW	HR	Y	67°	W	NW-5	Y	N	Y	2	2
	PM: 1:00	EW	LF	Y	58°	W	NW-5	N	N	Y	2	2
12	AM:											
	PM:											
13	AM:											
	PM:											
14	AM: 11:20	EW	HR	Y	69°	D	SW-3	N	N	Y	2	2
	PM: 3:00	EW	LF	Y	71°	D	SW-3	N	N	Y	2	2
15	AM: 8:00	AW	HR	Y	70°	D	S-1	N	N	Y	2	2
	PM: 12:47	AW	LF	Y	72°	D	SE-1	N	N	Y	2	2
16	AM: 9:00	AW	HR	Y	51°	D	S-2	N	N	Y	2	2
	PM: 2:00	AW	LF	Y	60°	D	S-0	N	N	Y	2	2

Date	Time of Inspection	Inspector's Initials	Area Inspected Haul Road or Landfill	Actively Working (Y/N)	Weather Conditions			Sweeper Active (Y/N)	Water Truck Active (Y/N)	Other Dust Control Measures Being Used	Is Dust Present (Y/N)	Comments
					Temperature	Dry/Wet/Humid	Wind Conditions/Currently Raining?					
17	AM: 8:14	EW	HR	Y	45°	D	N-2	N	N	Y	N	N
	PM: 2:10	EW	LF	Y	60°	D	N-1	N	N	Y	N	N
18	AM: 8:20	EW	HR	Y	61°	D	S-3	N	N	Y	N	N
	PM: 2:00	EW	LF	Y	70°	D	S-0	N	N	Y	N	N
19	AM:											
	PM:											
20	AM:											
	PM:											
21	AM: 10:00	EW	LF	Y	63°	W	SW-3	N	N	Y	N	N
	PM: 4:15	EW	HR	Y	67°	W	SW-3	N	N	Y	N	N
22	AM: 11:30	EW	LF	Y	61°	D	SE-7	N	N	Y	N	N
	PM: 1:45	EW	HR	Y	61°	D	SE-7	N	N	Y	N	N
23	AM: 11:30	EW	LF	Y	67°	D	SW-2	N	N	Y	N	N
	PM: 1:00	EW	HR	Y	69°	D	SW-2	N	N	Y	N	N
24	AM: 11:30	EW	LF	Y	67°	D	S-1	N	N	Y	N	N
	PM: 4:00	EW	HR	Y	69°	D	N-4	N	N	Y	N	N
25	AM: 11:15	EW	LF	Y	67°	D	N-2	N	N	Y	N	N
	PM: 2:45	EW	HR	Y	69°	D	NE-1	N	N	Y	N	N
26	AM:											
	PM:											
27	AM:											
	PM:											
28	AM: 9:30	EW	HR	Y	55°	W	S-1	N	N	Y	N	N
	PM: 4:00	EW	LF	Y	58°	W	SE-1	N	N	Y	N	N
29	AM: 11:30	EW	HR	Y	56°	W	S-2	N	N	Y	N	N
	PM: 2:00	EW	LF	Y	58°	D	S-1	N	N	Y	N	N
30	AM: 8:00	EW	HR	Y	54°	D	S-1	N	Y	Y	N	N
	PM: 3:00	EW	LF	Y	52°	D	SE-1	N	N	Y	N	N
31	AM: 10:00	EW	HR	Y	70°	D	N-4	N	N	Y	N	N
	PM: 2:00	EW	LF	Y	44°	D	N-1	N	N	Y	N	N

ATTACHMENT 2

Landfill Inspection Forms

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: Eddie Wamble

Date: 12-4-18

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berns	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually		
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12-3-18	Time: 1:03	Weather: Overcast 42°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	12-3-18 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12/6/18	Time: 9:00	Weather: Cloudy 37°	
Inspection Representatives			
Charah: E. Wambler			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wambler Print Name of Inspector Completing Form	E. Wambler Signature	12-6-18 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12-10-18	Time: 3:30	Weather: Clear 57°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble	E. Wamble	12-10-18	
Print Name of Inspector Completing Form	Signature	Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12-14-18	Time: 11:00	Weather: Cloudy 45°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	12-14-18 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12-24-18	Time: 8:30	Weather: Clear 34°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	N/A		
4d. Condition of letdowns	✓		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	12-24-18 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 12-27-18	Time: 8:14	Weather: 55° cloudy	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	12-27-18 Date	

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: Eddie Wamble

Date: 1-4-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually		
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-2-19	Time: 1:30	Weather: 38° Overcast	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble	E. Wamble	1-2-19	
Print Name of Inspector Completing Form	Signature	Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-4-19	Time: 9:25	Weather: 42° Rain	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	1-4-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-8-19	Time: 11:52	Weather: Clear 63°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble Print Name of Inspector Completing Form		E. Wamble Signature	1-8-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-11-19 1-11-19	Time: 11:30	Weather: Overcast 37°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble		E. Wamble	1-11-19
Print Name of Inspector Completing Form		Signature	Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-15-19	Time: 8:01	Weather: Over Cast 39°	
Inspection Representatives			
Charah: D. Scott			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
David Scott Print Name of Inspector Completing Form		David Scott Signature	1-15-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-18-19	Time: 1:30	Weather: 50° clear	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble	E. Wamble	1-18-19	
Print Name of Inspector Completing Form	Signature	Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-24-19	Time: 3:00	Weather: Clear 43°	
Inspection Representatives			
Charah: E. W. Amble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Print Name of Inspector Completing Form		Signature	Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 1-30-19	Time: 2:30	Weather: Clear 27°	
Inspection Representatives			
Charah: DAVID SCOTT			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
D. Scott Print Name of Inspector Completing Form		D Scott Signature	1-30-19 Date

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form

Inspection Conducted By: E. Washburn

Date: 2-1-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Bems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL WEEKLY LANDFILL INSPECTION FORM

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-4-19	Time: 1:00	Weather: Clear 64°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	2-4-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-6-19	Time: 2:15	Weather: Cloudy 68°	
Inspection Representatives			
Charah: D. Scott			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover			
2b. Condition of final cover	NA		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	NA		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
David Scott	David Scott	2-6-19	
Print Name of Inspector Completing Form	Signature	Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-12-19	Time: 2:22	Weather: Clear 49°	
Inspection Representatives			
Charah: D. Scott			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
David Scott Print Name of Inspector Completing Form		David Scott Signature	2-12-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-19-19	Time: 11:30	Weather: Overcast 37°	
Inspection Representatives			
Charah: Eddie Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble	E. Wamble	2-19-19	
Print Name of Inspector Completing Form	Signature	Date	

PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL WEEKLY LANDFILL INSPECTION FORM

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-21-19	Time: 9:30	Weather: Cloudy	
Inspection Representatives			
Charah:			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble		E. Wamble	
Print Name of Inspector Completing Form		Signature	
		2-21-19	
		Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-25-19	Time: 4:00	Weather: 54° Cloudy	
Inspection Representatives			
Charah:			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble	E. Wamble		2-25-19
Print Name of Inspector Completing Form	Signature		Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 2-28-19	Time: 4:00	Weather: Cloudy 36°	
Inspection Representatives			
Charah: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	/		
1b. Condition of exposed waste slopes	/		
1c. Condition of exposed waste grading	/		
1d. Signs of erosion or washouts	/		
1e. Signs of leachate seeps	/		
1f. Condition of dust control measures	/		
1g. Condition of landfill signage	/		
2. Cover System			
2a. Condition of interim cover	/		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	2-28-19 Date

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: E. Wamble

Date: 3-5-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berns	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually		
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL



WEEKLY LANDFILL INSPECTION FORM

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 3-5-19	Time:	Weather: Sunny 36°	
Inspection Representatives			
Name: BOBA Eddie Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Print Name of Inspector Completing Form		Signature	Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 3-12-19	Time: 3:35	Weather: 59° Cloudy	
Inspection Representatives			
Checked: <i>Bora E</i>			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
<i>Eddie Wamble</i>	<i>E. Wamble</i>	3-12-19	
Print Name of Inspector Completing Form	Signature	Date	

WEEKLY LANDFILL INSPECTION FORM

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 3-19-19	Time: 3:00	Weather: 59° Clear	
Inspection Representatives			
Inspector: <u>Bonal ; Eddie Wamble</u>			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
 Print Name of Inspector Completing Form	 Signature	3-19-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 3-25-19	Time: 1:26	Weather: Cloudy 61°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	3-25-19 Date	

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form

Inspection Conducted By: Bethie Wamble

Date: 4-1-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Barns	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4-3-19	Time: 10-16-19	Weather: Clear 61°	
Inspection Representatives			
BORAL: Eddie Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		Chimney Drain On ground
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	✓		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	4-3-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4-5-19	Time: 3:00	Weather: Cloudy 64°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	4-5-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4.11.19	Time: 3:00	Weather: Clear 81°	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		Chimney Drain Work ongoing
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	4-11-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4/15/19	Time: 2:29	Weather: Clear 66°	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	4-15-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4-23-19	Time: 3:15	Weather: 77 Overcast	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		Working on Chimney Drain clogging
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	N/A		
4d. Condition of letdowns	✓		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	4-23-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 4-30-19	Time: 3:50	Weather: 84° Cloudy	
Inspection Representatives			
BORAL : Eddie Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		Working on Chimney Drains
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	4-30-19 Date	

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form

Inspection Conducted By: E. W. Winkle

Date: 5-2-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Bans	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 5-6-19	Time: 1:39	Weather: 75° Clear	
Inspection Representatives			
BORAL: E. Whable			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Whable Print Name of Inspector Completing Form		E Whable Signature	5-6-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 5-13-19	Time: 11:00	Weather: Clear 70°	
Inspection Representatives			
BORAL: Paul Powers			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	X		
1b. Condition of exposed waste slopes	X		
1c. Condition of exposed waste grading	X		
1d. Signs of erosion or washouts	X		
1e. Signs of leachate seeps	X		
1f. Condition of dust control measures	X		
1g. Condition of landfill signage	X		
2. Cover System			
2a. Condition of interim cover	X		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	X		
2d. Condition of erosion control devices	X		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	X		
3b. Condition of leachate control panels	X		
3c. Status of leachate levels in disposal cells	X		
3d. Condition of leachate collection piping	X		
3e. Condition of cleanouts and headwalls	X		
3f. Condition of leachate transmission piping	X		
3g. Condition of leachate storage system	X		
4. Stormwater Control Facilities			
4a. Condition of culverts	X		
4b. Condition of ditches	X		
4c. Condition of diversion berms	X		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	X		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	X		
5b. Condition of well pads and pipe bollards	X		
5c. Access to wells	X		
6. Landfill Access Roads			
6a. Condition of main access road	X		
6b. Condition of active disposal area access road	X		
6c. Acceptable dust control measures	X		
7. Other Items			
7a.			
7b.			
Paul Powers Print Name of Inspector Completing Form		[Signature] Signature	5-13-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 5-20-19	Time: 11:30	Weather: Clear 77°	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wambke Print Name of Inspector Completing Form		E. Wambke Signature	5-20-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 5-28-19	Time: 1:00	Weather: 87° Partly Cloudy	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble		E. Wamble	5-28-19
Print Name of Inspector Completing Form		Signature	Date

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form



Inspection Conducted By: Eddie Wamble

Date: 6-3-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 6-3-19	Time: 8:30	Weather: Clear	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
 Print Name of Inspector Completing Form		 Signature	
		6-3-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 6-10-19	Time: 1:56	Weather: Clear 78°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		leachate collection
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble Print Name of Inspector Completing Form		E. Wamble Signature	6-10-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 6-18-19	Time: 9:05	Weather: Overcast 76°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	NA		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	NA		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble	E. Wamble	6-18-19	
Print Name of Inspector Completing Form	Signature	Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 6-24-19	Time: 1:30	Weather: Overcast	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	6-24-19 Date

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form

Inspection Conducted By: Eddie Wamble

Date: 7-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berns	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually		
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 7-1-19	Time: 8:45	Weather: 87 Clear	
Inspection Representatives			
BORAL : Eddie Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	Eddie Wamble Signature	7-1-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 7-9-19	Time: 2:30	Weather: 93°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	NA		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	NA		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature		7-9-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 7-15-19	Time: 11:00	Weather: Rain 74°	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	NA		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	7/15/19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 7-22-19	Time: 12:30	Weather: 82 cloudy	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble Print Name of Inspector Completing Form	E. Wamble Signature	7-22-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 7-30-19	Time: 220	Weather: Clear 79°	
Inspection Representatives			
BORAL : E. Wauble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation			
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wauble Print Name of Inspector Completing Form	E. Wauble Signature	7-30-19 Date	

PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form

Inspection Conducted By: E. Whible

Date: 8-2-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 8-5-19	Time: 10:30	Weather: 84° NE 1 Sunny	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature		8/5/19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 8-12-19	Time: 8:00	Weather: 85° Clear	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	8-12-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 8-20-19	Time: 8:20	Weather: Clear 89°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble Print Name of Inspector Completing Form		E. Wamble Signature	8-20-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 8-26-19	Time: 2:30	Weather: Clear 87°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	8-26-19 Date	

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: E. Wankel

Date: 9-1-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually		
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date:	Time:	Weather: 84° Clear	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wambke Print Name of Inspector Completing Form		E. Wambke Signature	9-3-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 9-9-19	Time: 2:30	Weather: 75° Clear	
Inspection Representatives			
BORAL TO: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	9-9-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 9-16-19	Time: 1:10	Weather: 101° Clear	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N-A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N-A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
E. Wamble Print Name of Inspector Completing Form		E. Wamble Signature	9-16-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 9-24-19	Time: 1:00 PM	Weather: Clear 79°	
Inspection Representatives			
BORAL :			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	9-24-19 Date	

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: E. W. Pugh

Date: 10-1-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Bems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 10-1-19	Time: 1:00	Weather: 91° Clear	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	10-1-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 10-7-19	Time: 11:00	Weather: Partly Cloudy 60°	
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature		10-7-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 10-14-19	Time: 3:00	71°	Weather: Clear
Inspection Representatives			
BORAL : E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	✓		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	10-14-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 10-21-19	Time: 2:00	Weather: 67° cloudy	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	10-21-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 10-28-19	Time: 4:00	Weather: Cloudy 58°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	10-28-19 Date	

**PLUM POINT ENERGY STATION CLASS 3N LANDFILL
Operations Inspection Form**

Inspection Conducted By: E. Wamble

Date: 11-4-19

DESCRIPTION	INSPECTION INTERVAL	PASS	FAIL*
Surface Water System			
Drainage Ditches & Culverts	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Berms	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Leachate Collection System			
Pumps	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Totalizers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission/Recirculation systems	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Storage facilities	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Landfill Final Cover System			
Erosion	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Ponded Water	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Settlement	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Vegetation	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Facility Roads			
Safety	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Routing	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Condition	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Mud	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Passable Width	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Emergency Response Equipment			
Fire Extinguisher	Check Quarterly Test Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Communication System	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
List of Emergency Phone Numbers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
First Aid Kits	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Waste Cell and Plant Grid Markers	Monthly	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Survey Markers	Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring Wells	Semi-Annually	<input checked="" type="checkbox"/>	<input type="checkbox"/>

* Explain failure on back of form.

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 11-4-19	Time: 1:55	Weather: 65°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	NA		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature		11-4-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 11-11-19	Time: 2:00	Weather: Raining	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	11-11-19 Date	

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 11-19-19	Time: 2:00	Weather: Clear 56°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form		E. Wamble Signature	11-19-19 Date

**PLUM POINT SERVICES COMPANY CLASS 3N LANDFILL
WEEKLY LANDFILL INSPECTION FORM**

Facility Name: Plum Point Energy Station, Class 3N Landfill			
Facility Address: 2732 South County Road 623, Osceola, AR 72370			
Date: 11-25-19	Time: 4:00	Weather: Clear 57°	
Inspection Representatives			
BORAL: E. Wamble			
Others:			
Weekly Inspection Observations			
	Acceptable	Needs Improvement	Comments (See Page 2 for Additional Comments)
1. General Operating Issues			
1a. General stability of landfill slopes	✓		
1b. Condition of exposed waste slopes	✓		
1c. Condition of exposed waste grading	✓		
1d. Signs of erosion or washouts	✓		
1e. Signs of leachate seeps	✓		
1f. Condition of dust control measures	✓		
1g. Condition of landfill signage	✓		
2. Cover System			
2a. Condition of interim cover	✓		
2b. Condition of final cover	N/A		
2c. Condition of vegetation	✓		
2d. Condition of erosion control devices	✓		
3. Leachate Collection and Storage System			
3a. Condition of leachate pumps	✓		
3b. Condition of leachate control panels	✓		
3c. Status of leachate levels in disposal cells	✓		
3d. Condition of leachate collection piping	✓		
3e. Condition of cleanouts and headwalls	✓		
3f. Condition of leachate transmission piping	✓		
3g. Condition of leachate storage system	✓		
4. Stormwater Control Facilities			
4a. Condition of culverts	✓		
4b. Condition of ditches	✓		
4c. Condition of diversion berms	✓		
4d. Condition of letdowns	N/A		
4e. Condition of stormwater ponds	✓		
5. Groundwater Monitoring Wells			
5a. Condition of well casings and locks	✓		
5b. Condition of well pads and pipe bollards	✓		
5c. Access to wells	✓		
6. Landfill Access Roads			
6a. Condition of main access road	✓		
6b. Condition of active disposal area access road	✓		
6c. Acceptable dust control measures	✓		
7. Other Items			
7a.			
7b.			
Eddie Wamble Print Name of Inspector Completing Form	E. Wamble Signature	11-25-19 Date	

ATTACHMENT 3

Landfill Inspection Photos



Photo 1. Rolled and sealed top of open disposal cell (Cell 3)



Photo 2. Active working face (Cell 3).



Photo 3. Haul road looking towards Plant



Photo 4. Water truck preparing to wet haul road



Photo 5. Landfill perimeter berm and stormwater ditch looking west



Photo 6. West slope Cell 1 under intermediate cover with leachate pond in background



Photo 7. Cell 1 from northwest.